Cornerstone Preschool & Nursery 401 North Second Street Brookhaven MS 39601 (601) 833-6128 Lic# 1562 Capacity: 190



Facility Inspection

County Lincoln				Date 2/4/2020				
Facility Name				License Number				
Purpose Renewal			Ca	npacity				
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	In Out	COS N//		Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities			COS	N/A
Room and playground capacity met Center capacity met License/complaint visible				Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair			. 🗆	
Certified food manager Sanitation Approved Garbage and garbage bins maintained Vector control maintained				Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,				
Water system approved and functioning Waste water system approved				and functioning				
and functioning Food service approved Possible Monetary Penalty				Electrical outlets protected Large appliances located properly Sinks and toilets working properly	A CAICA			
1	Monetary \$	y Penalty		Hot water at all sinks, not to exceed 120° Children barred from kitchen	T TO			
2				Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices				
4				single action approved and in good working order	-			
5Age/Child/Sta	\$			Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and				
1. Infant Q				in good working order				
2. 1/2 yrs old (a)				First aid kits stocked and easily accessi	ole			
3. 3/4 yrs old (8) 4. 4/5 yrs old (8)			-	Playground area clean, shaded, well drained and equipped and fence in good repair	1			
5.				Playground equipment meets standards				
6				Pool area clean, fenced, and adequately maintained				
· ·	1 11	0 4		Diaper changing stations adequate in number and each fully supplied (number)				
Center Director/Individual White Copy - Facility File Yellow (Mississippi State Department of Heal	Copy - Facility	///Cho Operator	12-	Child Care Representative	Har	y S Fo	orm No	. 281



District	Cornerstone Preschool & Nurser, 401 North Second Street Brookhaven MS 39601	Date <u>2/4/2020</u>
Name	(601) 833-6128 Lic# 1562 Capacity: 190)
Address	Center/Organiza	tion/Individual
Purpose Renewal	_	Director
Mileage Start	Mil	eage End
County Lincoln	Tele	ephone No
Time In 9:30	Time Out 12:45	Total Time
Findings/Comments \(\sigma\) \(\sigma \text{Clnvw ledge.}\)	reason for today's	lity, met with director
Kenewal inspe	ectron.	
After a tour	of the facility, 7	the following violations were
	Building / Erounds	
Deficiency: The free of to hules.	rn wall covering, ch	ciling shall be kept clean and hipped parnt, broken plaster and
Findings: Lice Stained Certifi	ense official observe	d in the three year old classroom four year old Classroom an
area were t	the civiling poeling	
POC/TA: DIA	ctor will be respons	ible for contaction facility
Marnentince		vollation. Director will also
the Violation	does not be-accus	be responsible for ensuring
Can be fox Feb. 18, 2020		cility has been given until
Katherine Reha	Osas Atlany	LO- Licensing Official COS-Corrected on Site TA-Technical Assistance POC-Plan of Correction LOS-Letter of Suitability

Mississippi State Department of Health

Revised 6-24-09

Form No. 287



Child Care Encounter (Continuation)

Date 2/4/2020

Facility Name Cornerstane Preschool Subchapter: Appendix D Playe	License No
Succhapter: Appendix D Plays	ground Satety
Deficiency: CPSC. 2.5.5 Wood and insectives: stant or s deferioration	Should be esther notinal and
and insectives stant or s	hould be treated to avoid
deferioration	
Finding: LO observed on the . Surrounding the Play area had deterioreted	Small playground, the wood burder areas were the wood had
PUC/TA: Director will have area on the burder. Pictures	maintenence to replace rotted of corrected violation can be fax
or -mailed on or before	Feb. 18, 2020 to LO.
Ruk 1.11.5(5) License official of	served in Annex were the Breschell
- STO TIOUSER IT DOUS PUTTINGEN ON	P. TOLLET OLIO NOT (Luck II) Dominaled
THE RY CEPIGINITY THAT ALL TOTICTS	intenence and toilet was fixed
and operational before 20 left	facility . 2/4/2020 COS
Rule 1. 11.8(9) 1000 observed in	Infant/Toddler room thermmeter
Pace I'm TING YOUTH THE TVOI A	I about height // tomuded
TA by explaining that All therm	uneters are to be placed in each
All thermemeters at child	Director immediately placed in each sheight. LOS on B14/2020
Green survey card was previded	
Mary due	"Class I and II violations may
Contact hours for state	result in a monetary penalty.
Contact hours for staff Fire Safety Form 333	Repeated violations may result in the doubling of a monetary penalty,
	suspension, or revocation of the license."
Katherin Richards Doffens Center Director/Designee/Individual Child Care Representa	White Copy - Facility File Yellow Copy - Operator



Cornerstone Preschool & Nursery 401 North Second Street Brookhaven MS 39601 (601) 833-6128 Lic# 1562

Capacity: 190

3	Program	Review	
	License No.		Date _

Yes No N/A 1.
25. Appropriate transportation policy followed {Subchapter 15}
26. Infant feeding schedules posted (Appendix C, VII)
Comments/Recommendations
Helpful Reminders: Please send your LO- 2 or 4 weeks menus, Fire Form, and Contact hours for staff. **License will be made available when all documents have been submitted and all violations corrected.
License to be issued: Regular Probational Restricted Fail Follow-up within days Probational Restricted Afterna Make Poince Child Care Representative

ty Inspection Results Cornerstone Preschool & Nursery 401 North Second Street Brookhaven MS 39601 Date (601) 833-6128 Lic# 1562 Capacity: 190 **CRITICAL VIOLATIONS** CORRECTION PLAN AND SCHEDULE No critical violations during this Inspection 92010 Permit No Charge Certified Manager ☐ 92020 Scheduled ☐ 92030 Followup ☐ 92015 Permit 1 \$30.00 ☐ 92040 Complaint 92011 Permit 2 \$100.00 ☐ 92050 Consultation 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00 ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection Facility Signature ☐ 92090 Restaurant Training Environmentalist Signature Permit Date Environmentalist Code White Copy - Facility Please Remit within 10 days to: Yellow Copy - PIMS Pink Copy- Environmentalist

Cornerstone Preschool & Nursery 401 North Second Street Brookhaven MS 39601 (601) 833-6128 Lic# 1562 Capacity: 190

re Playground Checklist

Inspection Date 2/4/2020

YES	NO	N/A □	Ι.	Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
2			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
P			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
4			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
-			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
4			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
-			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
T			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
			11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)
			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
			13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 36)
			15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49)
			16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
			18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
Direc	tor <u>L</u>	al	Lei	ene Rebacona Licensing Official _ Strany Slay