Prince Street Daycare Center 3 Prentiss Street Natchez MS, 39120 601-445-9428 #0207 Director: Edwin White



Cinia Care Facility Inspection

County Pages	Date 3.13.18
Facility Name	
Purpose Mid-Year C	Capacity
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair
Sanitation Approved Garbage and garbage bins maintained Vector control maintained	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,
Waste water system approved and functioning Waste water system approved and functioning Food service approved	and functioning Electrical outlets protected Large appliances located properly Sinks and toilets working properly
Possible Monetary Penalty 1 Monetary Penalty \$	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet
2.	nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order
5 \$ Age/Child/Staff Name	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and
1. Tyr/7/Caregiver/	in good working order First aid kits stocked and easily accessible
2. 3.4 17 Caregiver 2 3. 3.4 18 1 Caregiver 3 4. 2-3 18 1 Caregiver 4	Playground area clean, shaded, well drained and equipped and fence in good repair
5. Aferschool / 13 / Cargirer 5	Playground equipment meets standards
6	Pool area clean, fenced, and adequately maintained
Center Director/Individual El Ul	Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative
White Copy - Facility File Yellow Copy - Facility Operator	22-10-08 A Slay Church



Child Care Fncounter

District Prince Street Daycare Center	Date 5.13.18.
Name Natchez MS, 39120	License No
Address 601-445-9428 #0207 Director: Edwin White	Individual
Purpose Mid-Year	Director
Mileage Start	Mileage End
County Adams	Telephone No
Time In 3:04 Time Out 4:1	5 Total Time
Findings/Comments. Arrived at fac	cility and met with director
announced purpose of	Visit.
All incomplance at tin	ne of visit.
	·
"Class Land III.	violations may result in a
monetary pena	alty. Repeated violations
may result in t	he doubling of a alty, suspension, or
revocation of t	the license."
	0 0

Center Director/Designee/Individual

Offild Care Representative Human Revised 6-24-09

White Copy - Facility File Yellow Copy - Operator

Food Service Facility Inspection Results

PIMS ID Fac	Prince Street D 3 Prentiss Stree Natchez MS, 39 601-445-9428 Director: Edwin	et 120 #0207 • White	Date 3//3//8 AND SCHEDULE
All in Compi	l'ancc	Aissued	
92020 Scheduled 92030 Followup 92040 Complaint 92050 Consultation 92070 Plan Review/Const. 92080 No Inspection 92090 Restaurant Training	☐ 92010 Permit No Charge ☐ 92015 Permit 1 \$30.00 ☐ 92011 Permit 2 \$100.00 ☐ 92012 Permit 3 \$150.00 ☐ 92013 Permit 4 \$200.00	Barbara Greashaw Certified Manager Facility Signature Environmentalist Signature	TS exp 3/32/81 Licence Number
Please Remit within 10 days to:	Environmentalist Code	White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	lay Cumh

Child Care Licensure Playground Checklist

MYI

Cent	er Na	ame	tir	nce Street Day care Inspection Date 3/13/18
YES	NO	N/A		Genter / /
Ø			1.	Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
A			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)
D			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
P			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
D			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
D			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
D			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
	Lorend		11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14;
		10		2.5.2, pg 1 & 5.3.8.1, pg 37)
4			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
			13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
Z			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 46
1		favord	1.6	& CPSC 2.2.6, pg 6)
	Ц		15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 61)
No.			16.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 & CPSC 3.6, pg 16-17)
			18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
Direct	or	sidd differsion of the second	5.	Licensing Official Newsya Singlifus B. Slay Guston