

MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

County Hinds Date 9 100 1019								
Facility Name Prep Company Tutorial School-License Number 25CFP. FA-0664 Purpose Mid-Year Inspection / TA Capacity 183								
Purpose Mid- Year Inspection / TA Capacity 183								
All Iterns In Red Are Critical Qualified director present Proper staff to child ratio present	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In Out	cos	N/A				
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair							
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,	9444						
Waste water system approved and functioning and functioning Food service approved	and functioning Electrical outlets protected Large appliances located properly Sinks and toilets working properly							
Possible Monetary Penalty 1	Hot water at all sinks, not to exceed 120°							
3 \$								
5\$	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and							
1. 4 NWN-16 MON (4) 2 CAREGRER	in good working order							
2. I de la [a] I afflatore a	First aid kits stocked and easily accessib	ole						
3. 1-1 4 (9) 1 (Hughver) 4. (2) 1 (2)	drained and equipped and fence in good repailsee							
5. 3 year (b) Chrigaren	Playground equipment meets standards Pool area clean, fenced, and adequately							
7. 4-5 year (5) [CAREGINER	Diaper changing stations adequate in number and act fully supplied (number)							
Center Director/Individual Ratliff	Child Care Representative	Jana (an	2 -				
White Copy - Facility File Yellow Copy - Facility Operator Mississippi State Department of Health 12-10	D-08	Jenie	orm No.	281				



Child Care Encounter

District5		Date 4/26/2019
Name Prep Company Tutor	rial School - North License No. 25 St. Jackson, MS 3920 Center/Organization Individual	CFPFA-0664
Address 5332 N. State	Center/Organization/Individual	00
Purpose Mid-year Inspec	tion/TA Director Vennifer	Ratliff
Mileage Start	Mileage End	A ALCONOMIC
County Hinds	Telephone No. <u>401-3</u>	362-4653
Time In 3:45 p.m	Time Out 4:06 pm Total Time	
Findings/Comments The luens	sing officials met with direct	or, Jennifer Ratliff.
The purpose for this vi	sit was for a mid-year in	pection/TA Visit.
These well no degli	ct Nevise love @ Wol-364	1 Vit. If there are
		11
A childcare Surrey	WAS 1874 With JEAM FER LA	11.77.
	1	
s		
()—————————————————————————————————————		
	91	
alan - and H and	1 - 1 - 1 - 1 Al cal vide - 1 a Ma.	2101 1 0000 Hz
TELEPHOLINICATION A	MA SUNT THE COUNTY OF	A A M. Surjewy
Center Director/Designee/Individual	Chief Care Representative	White Copy - Facility File Yellow Copy - Operator
Mississippi State Department of Health	Revised 6-24-09	Form No. 287

Food Service Facility Inspection Results

PIMS ID Fac	ility Name, Address 533 2	N. State St. Jackson, ms Date	
25CFPFA-NGYP	rep Company Tu	torial School-North 4/26/19	7
	1	CORRECTION PLAN AND SCHEDULE	
No critical violations		PASS Kitchen Received "A"	
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training Permit Date	□ 92010 Permit No Charge □ 92015 Permit 1 \$30.00 □ 92011 Permit 2 \$100.00 □ 92012 Permit 3 \$150.00 □ 92013 Permit 4 \$200.00 Environmentalist Code	Certified Manager Licence Number 2	300
Please Remit within 10 days to:		White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	, , ,

Playground Checklist Center Name Prep Company Tutorial School-North Inspection Date 4/26 Name of Licensing Official Denise Love Dana Jones License # 25CFPFA - 0664 NO Playground fence less than 31/2" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48) 2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48) Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8) AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47) 4. Transformers located a minimum of 30 ft. from playground? (Rule 1.11.9 (5), pg 47) N/A 5. No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10) Therewas standing water due to rain yesterday. Toys & equipment in good repair? (None broken/deteriorating) (Rule 1.10.2 (2), pg 36) Sidewalks provide smooth walking surface? (No trip hazards) (CPSC 3.6, pg 15) A NIA 8. All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47) Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15) No trees on Playground. Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40) 11. NA NA 12. If swings are present, are S-hooks in good repair? If not, state deficiency No Swings present (CPSC 3.2, pg13) If slide is present, is exit height/exit zone adequate? If not, state deficiency 13. (CPSC5.3.6.4-5 pgs 34-35) Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15) No Spring rockers N/A 14. Is age-appropriate equipment being used? If not, state which pieces are inappropriate 15. (Rule 1.10.2, pg 36) Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49) Is adequate shade present on the playground? (CPSC 2.1.1, pg 5) No trees present. 17. Are concrete footings located a minimum of 6" beneath the surface? (Rule 1.10.2 (2), pg 36) 18. Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5) NA 19.

Licensing Official 1