

MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

	County Let Date 2-11-2					
	Facility Name Changing Lives		License Number	و الحله		
	Purpose Midyear	_ Cap	pacity			
	All Items In Red Are Critical Jons In Out COS N/A Qualified director present Proper staff to child ratio present Room and playground capacity met Center capacity met		Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In Out	cos	N/A
	License/complaint visible Certified food manager		Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair			w .
	Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning Waste water system approved and functioning		Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,			
	Food service approved Possible Monetary Penalty		and functioning Electrical outlets protected Large appliances located properly			
	1 Monetary Penalty 2 \$		Sinks and toilets working properly Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet			
	3\$		nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order			
om2	Age/Child/Staff Name		Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers	Z 0		
em ³	1. NO Children 2. NO Children 3. Tufata a communication		and thermometers placed properly and in good working order First aid kits stocked and easily accessible			
rms em le	4. 1,13, Caregivers 3-4		Playground area clean, shaded, well drained and equipped and fence in good repair Not inspected			
Rm7 Rme			Playground equipment meets standards Wood 'n Spected Pool area clean, fenced, and adequately maintained			
•	Center Director/Individual		Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative			Dult
	White Copy - Facility File Yellow Copy - Facility Operator Mississippi State Department of Health	12-10-	08	Form	n No. 2	281

Form No. 287



MISSISSIPPI STATE DEPARTMENT OF HEALTH

	\mathcal{T}	Child Care	Encounter		
	District				Date_ 2-11-2 [
	Name having LIVES		License No.	134	
	Address 136 S. Tho	Center/Organizati	Tupelo		38801
	Purpose_Midyear		irector_Shery	Tran	
	Mileage Start	Mile	age End	C	
	County_Lee	Telep	hone No. 462.2	05-4	153
		Out 2:00	Total Time	2	
	Findings/Comments Here to (arrival 10 met with	Conduit a	Midyeur in director designee	Spects Te	on. Upon nifer Baites.
_ ·	Staff-to-child ratio i Kitchen reid an A; p Staff 121's in	n Complian	ance Violations		
	T.A. Provided on Refacility Shall Mainta Children MSDH 121'S.	lule 1-6.3	()	Chi bot On a	ld Care h Staff and Child needing Next 14
(=	Planground was not to inclement weather	er. (Raining	d on tod	laij	visit du
-					
_					
m re	Class I and II violations may result in a nonetary penalty. Repeated violations may esult in the doubling of a monetary penalty, uspension, or revocation of <i>the</i> license."				
7	Alury Ture Senter Director/Designee/Individual	Child Care Repres	entative Utt	White Yellov	Copy - Facility File V Copy - Operator

Mississippi State Department of Health

Food Service Facility Inspection Results

PIMS ID F	acility Name, Address		Date
	1 100	13 mg Livis	arms ()
	Thorna and	s St. Tapelly, 115	12-11-21
CRITICAL VIO	DLATIONS	CORRECTION PLAN AND	D SCHEDULE
-NO Critic			
Pass			
☐ 92020 Scheduled	☐ 92010 Permit No Charge	Shared Tracker	
92030 Followup	92010 Permit No Charge	Certified Manager Li	cence Number
☐ 92040 Complaint			Crit
☐ 92050 Consultation ☐ 92012 Permit 3 \$150.00		V. Comment	
☐ 92070 Plan Review/Const. ☐ 92013 Permit 4 \$200.00		10	
☐ 92080 No Inspection	40 000	Facility Signature	
92090 Restaurant Training		Merch	/ww/
Permit Date Environmentalist Code		Environmentalist Signature	7att A
Please Remit within 10 days to:		White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	
te 75			

Child Care Licensure Playground Checklist

C	enter	Nam	ie (Many Lives Inspection Date 2-11-21
Y	ES_N	O N	A	
A] 1.	Playground fence less than 3½" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
Ø			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
			11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)
			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC 5.3.6.4-5 pgs 34-35)
			13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1)2, pg 15)
Ц			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate
			15.	Is playground area clean & free of hazards? If not, state deficiency (Rule 1.10.2, pg 36)
			16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
			18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
Direct	or			Licensing Official
X		$) \setminus c$	ux	proud not inspected due to inclement er. (Raining)
Weather. (Kaining)				