

MISSISSIPPI STATE DEPARTMENT OF HEALTH **Child Care Facility Inspection** County Date Facility Name License Number Capacity Other Items - Must be corrected COS Children's belongings separated/stored Evacuation plans posted All Items In Red Are Critical Out COS N/A Menus posted and served Qualified director present Plan of activities Proper staff to child ratio present Room and playground capacity met **Building and Grounds** Center capacity met Walls, ceilings, floors, toys, equipment License/complaint visible clean and in good repair Certified food manager Lighting approved **Sanitation Approved** Heating/cooling approved Garbage and garbage bins maintained Ventilation adequate Vector control maintained Glass approved and shielded Water system approved and functioning Telephone on premises, available, Waste water system approved and functioning and functioning Food service approved Electrical outlets protected Large appliances located properly **Possible Monetary Penalty** Sinks and toilets working properly Monetary Penalty Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and in good working order 2. First aid kits stocked and easily accessible 3. Playground area clean, shaded, well drained and equipped and fence in good 4. 5. Rlayground equipment meet 6. Diaper changing stations adequate in number and each fully supplied Center Director/Individual Child Care Representative

White Copy - Facility File Mississippi State Department of Health

Yellow Copy -Facility Operator

12-10-08

Form No. 281

Form No. 287



MISSISSIPPI STATE DEPARTMENT OF HEALTH

\mathcal{A}	Child Care Encounter	111111111111111111111111111111111111111
District_O		Date 1119 W 0
Name A Child PACE	License No.	41FA-5582
Address 19 N. Myden St.	Center/Organization/Individual	
Purpose Comonth TA	Director_STPCCY	HAWRINS
Mileage Start	Mileage End	
County tumm fu	Telephone No. (462) 24	7-2200
	e Out 202 M Total Time_	
Findings/Comments TO PUPOH	TOR VUH IT TOR A	STA MONTH) - ENSPECTION
any questions of con	difficiencie on todays vis	it they are leven 887 4951.
A ChildCARD Suprey W	OS lest with stacey Hawle	DS:
	/ / / / / / / / / / / / / / / / / / / /	1
CLASS I and I VID Repended Violations M Minchany penary, Sup	ATURS MAY PLYWH THE A VAN PLYWHILL IN HO CONDING EDEWN, OR PLANCATION of HY	MoneAffly Penatty.
Center Director/Designee/Individual	Child-Care Representative	White Copy - Facility File Yellow Copy - Operator
Mississippi State Department of Health	Revised 6-24-09	Form No. 287

Food Service Facility Inspection Results

PIMS ID Fac	ility Name, Address	19 N. HOLDEN SI. Date 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
CDITICAL VIOL		CORRECTION PLAN AND SCHEDULE
M Charlest Notes	ions observed	Met complainer Adaly Red 'A'
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training Permit Date Please Remit within 10 days to:	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00 Environmentalist Code	Certified Manager Licence Number Facility Signature Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist

Child Care Licensure Playground Checklist

Cente	r N	ome l	Ar	MUS MAN Inspection Date 1114 1078
			4	Inspection Date 1111 1 2010
YES	NO	N/A □	1.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
Z.			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
9			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)
Z,			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
d			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
		9	7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
		L	8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
é			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
		Z	10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
		6	11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14;
_	_	_	10	2.5.2, pg 1 & 5.3.8.1, pg 37)
		<i>y</i>	12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
		Ø,		Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
		7	14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 46 & CPSC 2.2.6, pg 6)
Z			15.	Is playground area clean & free of hazards? If not, state deficiency.
1	П	П	1 6.	(Rule 1.11.11 (1), pg 61) Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
	_ _ (N	04	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 &
4	_ >	Dr.	P 1.	CPSC 3.6, pg 16-17)
6		4	718.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15),
Directo	or	SA	acer	Jaw Kins Licensing Official DN Ove
				\mathcal{C}