

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Bountiful Blessing Preschool, LLC 2353 Carrollton Road

License# 3943 Capacity 82
Director: Barbara Reed

Chil	d (Car	e	Faci	lity	Ins	pe	cti	on	l

nada MS, 38901 ense# 3943 Capacity 82		Date_0/-19-209-1			
ector: Barbara Reed		License Number			
Purpose Mich year		Capacity			
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	n Out COS N/A	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In Out	COS	N/A
Room and playground capacity met Center capacity met License/complaint visible Certified food manager		Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair	A O		
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning Waste water system approved		Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available, and functioning	A MANA A		
and functioning Food service approved Possible Monetary Penalty 1	Monetary Penalty	Electrical outlets protected Large appliances located properly Sinks and toilets working properly Hot water at all sinks, not to exceed 120°	M (SM)		
	\$	Children barred from kitchen Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices			A
4. 5.	\$	single action approved and in good working order Exits unobstructed Required smoke detectors, carbon	A 0		
Age/Child/Staff N 1. 115-6-Staff H 2. The Age/Child/Staff N	lame / よの井々	monoxide monitors, fire extinguishers and thermometers placed properly and in good working order First aid kits stocked and easily accessib			
3. 2 yrs - 9 - Staff = 4. 3 yrs - 9 - Staff = 5. 3 yrs - 8 - Staff = 5.	+3 +44 +45	Playground area clean, shaded, well drained and equipped and fence in good repair Playground equipment meets standards	A 0		
6. 7.)	Pool area clean, fenced, and adequately maintained			本
Center Director/Individual Box	A.R.	Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative	Kalin	0(
White Copy - Facility File Yellow Copy Mississippi State Department of Health	- Facility Operator 1	2-10-08	Fo	OOJC orm No.	28

Form No. 287



MISSISSIPPI STATE DEPARTMENT OF HEALTH

Division of	Bountiful Blessing Preschool, LLC	Date <u>01/19/2021</u>
District	2353 Carrollton Road	Date () / 1 9001
Name	Grenada MS, 38901	/
Address	License# 3943 Capacity 82	
3 0	— Director: Barbara Reed	
Purpose Md- 4000.	Director	
Mileage Start	Mileage End	
County Mrchael	Telephone No. (663)	227-9693
Time In T	ime Out 1100 Total T	ime
Findings/Comments 1000	eumid-year on	spection, the
licenshop office	ucio most With Ster	phance forrell
designed 1)
1 November 1 Proto 11	2/6	11 (300) 100) 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Deficiency Rue Ik	of an alpha and a	Car anne what
The state of the s	TOP (BYTHEINDING) (ODIES OF	the Mont Contricology
Immunization complic	local book of all and another	potn staff and Unidien
at the feather the	ratorio un cilla de tracer	separate numeral
Christopacox 10/26/7	of 1011 sof and and	O stone (1) at them
anond: The man	and different opens	ed placen (11) (hidren
TURNOUT C	CHUTCHY MADT 19 100	m tolade stromet
With Hours of	accompany pratty	tolden inder
ta the owner Bo	whole Read Will ON	SWETT VOT WILL
THICK YOUR OF GUILD	ent morrish pince	
10 Montan I on	alawowallal	
A ORCHICA O TON	Dragerow Co	
Rigoben Moch roch	lotte opeld'A"	
THE COURT OF CO	Clery, Cresce 1)	
B 100	YNOG Shows	01 111111111111111111111111111111111111
Jack K	ALANNA OF TOO	White Copy - Facility File Yellow Copy - Operator
Center Director/Designee/Individual	Child Care Representative /\	/\

Revised 6-24-09

Mississippi State Department of Health

Food Service Facility Inspection Results

ncility Name, Address		Date	
		01/19/0001	
DLATIONS	CORRECTION PLAN AND SCHEDULE		
92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00 Environmentalist Code	Certified Manager Facility Signature Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist		
	□ 92015 Permit 1 \$30.00 □ 92011 Permit 2 \$100.00 □ 92012 Permit 3 \$150.00 □ 92013 Permit 4 \$200.00	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00 Facility Signature Environmentalist Code Environmentalist Signature White Copy - Facility Yellow Copy - PIMS	

Center Name YES NO N/A D D 1.	Bountiful Blessing Preschool, LLC 2353 Carrollton Road Grenada MS, 38901 License# 3943 Capacity 82 Director: Barbara Reed Playground tence less than 3 ½" trom surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
□ □ 3.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
7 2 2 3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
X 0 0 4. X 0 0 5.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
<i>p</i> , 0 0 5,	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2.(2)
D 0 7.	orderwarks provide smooth walking surface? (no trip hazards) (CPSC 3.6, 75.15)
<u> </u>	twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg. 47)
9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
Д □ □ 10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
	If swings are present, are S-hooks in good repair? If not, state deficiency
	If slide is present, is exit height/exit zone adequate? If not, state deficiency
V = -	(CPSC5 3 6 4 5 pgg 24 25)
	The spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
<i>y</i>	Is age-appropriate equipment being used? If not, state which pieces are inappropriate
火 □ □ 15.	is playground area clean & free of hazards? If not, state deficiency.
X 0 0 16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
A 0 0 17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
□ □ 18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
	2.5.5)
Director Jan	Licensing Official Holmy Shows