

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Facility Inspection

County Le Hore			Date 12/18/2000			
Facility Name MWU Development Center License Number 42 CDGF - 4869						
Purpose Kenewal		Сар	pacity_53			
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	In Out COS	N/A	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In Out	COS	N/A
Room and playground capacity met Center capacity met License/complaint visible Certified food manager			Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair			
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning			Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,	0000		
Waste water system approved and functioning Food service approved			and functioning Electrical outlets protected Large appliances located properly			
Possible Monetary Penalty 1	Monetary Penal \$	ty	Sinks and toilets working properly Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet			
3	\$\$ \$		nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order			
5			Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers			
1. Three 5 one Co	oregiver		and thermometers placed properly and in good working order First aid kits stocked and easily accessible.			
3. 4.			Playground area clean, shaded, well drained and equipped and fence in good repair			
5.			Playground equipment meets standards			
6			Pool area clean, fenced, and adequately maintained			
Center Director/Individual_//_	lebrah K.	Min	Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative	Ind		

White Copy - Facility File Yellow Cop Mississippi State Department of Health

Yellow Copy - Facility Operator

12-10-08

Form No. 281



MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Encounter

District 3	Date 12/18/2020
Name MUSU Development Center License No. 42CDGF	-4869
Address Robert Clark JR Lane, I Ha Bena, MS 32941 Center/Organization/Individual	
Purpose Kenewal Director Dr. D. Minoe	
Mileage Start Mileage End	
County Le Hore Telephone No. 462-254-31	05
Time In 2.02 Time Out 2:49 Total Time	
Findings/Comments This visit is for Renewal inspection	For Child Care
ficerise.	
The licensing official did not observe any the building kitchen, or playground during the	Concerns with
The Durang Kilcher, or playground during the 1	enrival inspection.
No concerns observed with staff and childre	n records.

	1
Licensing agency at 601.364.2827 or Shundray	ivens@msth.ms.gov
THE TISTING GOT GOT GOT GOT SAST BY STIONAVALLY	IVERSOI II SIK. MS . GOO
	A A CONTRACTOR OF THE CONTRACT
	energy and advanced by the second
Center Director/Designee/Individual Child Care Representative	White Copy - Facility File Yellow Copy - Operator



Child Care Program Review

Facility Name MUSU Development Center License No. HSCDGF-4869 Date 12/18/2000
Ves No N/A 1.
Pass – License to be issued: Regular Probational Restricted

days

Director

Designee

Child Care Representative

Follow-up within

Food Service Facility Inspection Results

PIMS ID Fac	cility Name, Address MWU	Development Center	Date
42CDGF-4869	Robert (Development Center Mark Dr. Itta Bena, 38941	12/18/2000
CRITICAL VIO		CORRECTION PLAN AN	D SCHEDULE
No violation	15	"A"	
 □ 92020 Scheduled □ 92030 Followup □ 92040 Complaint □ 92050 Consultation □ 92070 Plan Review/Const. □ 92080 No Inspection 	☐ 92010 Permit No Charge ☐ 92015 Permit 1 \$30.00 ☐ 92011 Permit 2 \$100.00 ☐ 92012 Permit 3 \$150.00 ☐ 92013 Permit 4 \$200.00	Certified Manager I	icence Number
Permit Date	Environmentalist Code	Environmentalist Signature	(en)
Please Remit within 10 days to:		White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	

Child Care Licensure Playground Checklist

Center Name	WU Deiterpment Center Inspection Date 12/18/2020
YES NO N/A	
	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
□ □ □ 3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
0 0 4.	AC units, high voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
2 0 0 5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
₽ □ □ 6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
P 0 0 7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
₽ □ □ 8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
D 0 9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC)
□ □ □ 10.	3.4, 3.5, pg 15) Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)
0 0 12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC 5.2, pg15) (CPSC 5.3.6.4-5 pgs 34-35)
0 0 12 13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
0 0 14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 36)
0 0 15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49)
0 0 16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
U 0 17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
0 0 18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
Director Alebo	who Killer Licensing Official Madul