

MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

County Re	Date			
Facility Name Mini Minutes License Number Lele 99				
Purpose_Midyear	Capacity			
	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities			
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair			
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,			
Waste water system approved and functioning Food service approved Possible Monetary Penalty	and functioning Electrical outlets protected Large appliances located properly Sinks and toilets working properly			
Monetary Penalty 1 \$	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet			
2. \$ 3. \$	nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order			
4 \$ 5 \$	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers			
Age/Child/Staff Name 1. 1, 7, Caregiver 1 2. No children	and thermometers placed properly and			
22. No Children 33. 2, 8, Carestver 2 24. 3, 10, Carestver 3	Playground area clean, shaded, well drained and equipped and fence in good repair			
15. 2,12, Caresiver 4	Playground equipment meets standards			
46. Intents, 7, Caregivers	Pool area clean, fenced, and adequately maintained			
S_{1} h_{1}	Diaper changing stations adequate in number and each fully supplied (number)			
Center Director/Individual White Copy - Facility File Yellow Copy - Facility Opera	Child Care Representative			
White Copy - Facility File Yellow Copy - Facility Opera Mississippi State Department of Health	12-10-08 Form No. 281			



Child Care Encounter

The Care Electrical	Date $10-6-21$
District 1 1 1 5 C C P C	6699
290 4111 1 51 7101 116	38801
Center/Organization/Individual	
Purpose Midyear Director Eunic	Sha Price
Mileage Start Mileage End	Citil All A
County LC Telephone No. 1662	- 844 - 0450
Time In Time Out To	tal Time
Findings/Comments Hery to Conduct a Midyea arrival Lo Met with designee Ciar	r inspection. Upon
Staff-to-Child ratio in Compliance Stoff 121's and Los's in Compliance Sitehen recid an A', No critical violations Playground in Compliance.	on today visit.
T.A. Provided on Rule 1.6.3 (8) All facility's are required to maintain a note 121's MSDH Forms. Lo observed for a Current 1210 Facility will Submit Form within next 14 days.	licensed Child Care book with Carry ar children needing a copy of 129
Repeated Violations May result in the clow Sas Pusion of revocation of the literse Limit 8h a Drive Center Director/Designee/Individual Child Care Representative	in a Monday Penalty. 613 6 f a Monday Penalty. White Copy - Facility File Yellow Copy - Operator
Mississippi State Department of Health Revised 6-24-09	Form No. 287

Mississippi State Department of Health

Food Service Facility Inspection Results

	lity Name, Address		Date
Ka 33	in Wilford St. 7	upelo, Mis 59801	10-6-21
CRITICAL VIOL	ATIONS	CORRECTION PLAN	AND SCHEDULE
-No CVitic	al Violations		
on toda	P VISit.		
The state of the s			
Passed			
			The state of the s
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const.	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00	Certified Manager Tummy Sat	Licence Number
☐ 92080 No Inspection ☐ 92090 Restaurant Training Permit Date	Environmentalist Code	Facility Signature Environmentalist Signature	ha Dice
Please Remit within 10 days to:	7/2	White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	

Child Care Licensure Playground Checklist

Center Name	ini Miractes Inspection Date 10-60-21
YES NO N/A	
	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
Z 0 0 2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
0 0 0 3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
Z 0 0 5.°	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
\angle 0 0 6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
e 0 0 7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
<u> </u>	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC
<u> </u>	3.4, 3.5, pg 15) Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pgl3)
0 0 2 12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC 5.3.6.4-5 pgs 34-35)
O O Z 13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
0 0 / 14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 36)
2 0 0 15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49)
Z 0 0 16.	Is adequate shade present on the playground? (CPSC 2.1.1. pg 5)
	Are concrete footings located at least 6" beneath the surface? (Rule 1 10 2 (2), pg 36)
	Is wood smooth? Documentation provided that wood has been properly treated. ICPSC
Director Lun Sh	$(2, \hat{2}, \hat{3})$