

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Eva Covington Head Start Center 145 Teasdale Road

hil	d	Care	Fa	cilit	y I	nsp	ec	tic	or	

Charleston Ms 38921	Date (06Q) 647-5352
License # 4194 Capacity 158  Director: Catherine Hubbard	
	License Number
Purpose Med Hol-	Capacity <u>158</u>
All Items In Red Are Critical  Qualified director present  Proper staff to child ratio present	Other Items - Must be corrected In, Out COS N/A Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities
Room and playground capacity met  Center capacity met  License/complaint visible  Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning Waste water system approved	Lighting approved  Heating/cooling approved  Ventilation adequate  Glass approved and shielded  Telephone on premises, available, and functioning
and functioning Food service approved  Possible Monetary Penalty	Electrical outlets protected  Large appliances located properly  Sinks and toilets working properly  Hot water at all sinks, not to
1 Monetary Penalty	exceed 120°  Children barred from kitchen  Vending machine snacks meet
3\$ 4\$	nutritional guidelines, if present  Exits, doors and fastening devices single action approved and in good working order
5\$	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers
1.	and thermometers placed properly and in good working order
2. NO CONCINED	First aid kits stocked and easily accessible Playground area clean, shaded, well
4. Present	drained and equipped and fence in good repair
5.	Playground equipment meets standards
<ul><li>6.</li><li>7.</li></ul>	Pool area clean, fenced, and adequately maintained
Center Director/Individual Ah.	Diaper changing stations adequate in number and each fully supplied (number)  Child Care Representative

White Copy - Facility File

Yellow Copy - Facility Operator

Mississippi State Department of Health



MISSISSIPPI STATE DEPARTMENT OF HEALTH

District	Child Care Encounter Eva Covington Head Start Center 145 Teasdale Road	Date 01/14/809/
Name	Charleston Ms 38921	
Address	License # 4194 Capacity 158  Director: Catherine Hubbard	
Purpose Mid-Year	Director	
Mileage Start	Mileage End	
County Tallahatahele	Telephone No. (469) 647	1-5353
Time In 9100 AM	Time Out Total Time	
Findings/Comments Here to	or mid-your inspects	on Upon Hubbard.
Reclicersus Jump Jame	of impertion.	n present
Still Cottol of I	Jeff MSPH 121 form- Sultability-Complian ad lettle procle A	compliance.
Building Groun	D-complianco.	
Unid Con Quest	ionnaud lift @ K	2011 del
Mars I arall	121010-tran & moul , in Not-	tin a manalarit
Denalty Benedital	Euspension or which	t in the doublide
Center Director/Designee/Individual	Child Care Representative	White Copy - Facility File Yellow Copy - Operator

## **Food Service Facility Inspection Results**

PIMS ID	Facility Name, Address		Date (C) 114 Level (C)
CRITICAL	VIOLATIONS	CORRECTION PLAN AN	D SCHEDULE
10 (10)60	e Wiolandis		
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection	☐ 92010 Permit No Charge ☐ 92015 Permit 1 \$30.00 ☐ 92011 Permit 2 \$100.00 ☐ 92012 Permit 3 \$150.00 ☐ 92013 Permit 4 \$200.00		Licence Number
92090 Restaurant Training Permit Date	Environmentalist Code	Facility Signature  Environmentalist Signature	
Please Remit within 10 days	to:	White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	

Center Name	145 Teasdale Road Charleston Manager
YES NO N/A	Charleston Ms 38921 Inspection Date O//U/DO/
	Director: Catherine Hubbard Playground rence less man 3 /2 from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
₹ □ □ 2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
▼ □ □ 3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
<b>P</b> 0 0 5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
<b>X</b> 0 0 6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36) Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
□ □ 8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
✓ □ □ 10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
	If swings are present, are S-hooks in good repair? If not, state deficiency
A 0 0 12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency
	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
	is age-appropriate equipment being used? If not, state which pieces are inappropriate
	Is playground area clean & free of hazards? If not, state deficiency.
<b>A</b> 0 0 16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
<b>A</b> 0 0 17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
7 0 18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
Director CC	Licensing Official Roma Shows