

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Facility Inspection

County_Hinds	Date
Facility Name Sherry's Preschool	License Number 1530
Purpose Midyear TA Cap	pacity_66
All Items In Red Are Critical Qualified director present Proper staff to child ratio present In Out COS N/A U U U U U U U U U U U U U U U U U U U	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities
Qualified director present Proper staff to child ratio present Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,
Waste water system approved and functioning	and functioning
Possible Monetary Penalty 1	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet
3\$	nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order
Age/Child/Staff Name	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and
1. lomo-lyr: 5. CG1 2. 2-3vr: 7. CG2	in good working order
3. 4-5yr.5·CG3 4.	Playground area clean, shaded, well drained and equipped and fence in good repair
5.	Playground equipment meets standards
6. 7.	Pool area clean, fenced, and adequately maintained
Center Director/Individual Sawathe Dog	Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative

White Copy - Facility File

Yellow Copy - Facility Operator

Mississippi State Department of Health

12-10-08

Form No. 281

Mississippi State Department of Health

Form No. 287



Child Care Encounter

District_5	Cilia Care Encounter	Date 1.16.2020
Name Sherry's Presche	License No. 153	30
Address 887 Magnolia	Rd. Clinton ms Center/Organization/Individual	
Purpose Midycar TA		Chappell
Mileage Start	Mileage End	
County Hinds	Telephone No. 60 924	-8503
Time In 022	Mileage End	
Findings/Comments Upon arr	nival licensing officions ba Davis.	al met with
designer, samanti	ha Davis.	
Technical Assistance	e provided on the follow	wing:
kule 1.6.3 tack to m	oust have a current alph	pabetical childrens
create a concret al	phabetical roster for d	n Director and
Designer are respon	sible parties to be s	ure this is
	H recur. Please fax or s	
a copy of voster once		
Thanks for all you	dois	
	A: 11	
Survey card left	w designee	
9		
		Class I and II violations may result in a
		nonetary penalty. Repeated violations nay resulted in the doubling of a
	r	nonetary penalty, suspension, or evocation of the license.
Samotha Das	Alra Herman	White Copy - Facility File Yellow Copy - Operator
Center Director/Designee/Individual	Child Care Representative	

Revised 6-24-09

Food Service Facility Inspection Results

PIMS ID Fac	lity Name, Address	d.	Date
1530 C	inton ms 39051	0	1.16.5050
CRITICAL VIOI	ATIONS	CORRECTION PLAN ANI	SCHEDULE
No violations of today's visit	ited on	NA	
*			
Facility r	ecerved		
92020 Scheduled 92030 Followup 92040 Complaint 92050 Consultation 92070 Plan Review/Const. 92080 No Inspection 92090 Restaurant Training Permit Date Please Remit within 10 days to:	☐ 92010 Permit No Charge ☐ 92015 Permit 1 \$30.00 ☐ 92011 Permit 2 \$100.00 ☐ 92012 Permit 3 \$150.00 ☐ 92013 Permit 4 \$200.00 Environmentalist Code	Certified Manager Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	icence Number

Child Care Liceusure Playground Checklist

			CL	emil's Preschool Inspection Date 162000
Cent			Sh	
YES	ОИ	N/A	1,	Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
4			2.	2 entrances/exits, with one being remote from the building? (Rule 1,11.9 (8), pg 00)
×			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)
4	\Box		4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
1			5.	No standing water present on playground or in/on playground equipment or walkways?
/			6.	(CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61) Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
1			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
X			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
/ /			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC
			10.	3.4, 3.5, pg 16) Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
1			11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14, 2.5.2, pg 1 & 5.3.8.1, pg 37)
X		C	12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
/	6			Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1 2 & CPSC 5.3.7. pg 36-37)
19			13.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1 10.2, pg 46 & CPSC 2.2.6, pg 6)
6	_	1 =] 15.	
d	/ _	1 [16	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.11, pg 5)
P	<u> </u>] [17	Are concrete footings located at least 6" beneath the surface? (Rule 1:10.2 (2), pg 40 (CPSC 3.6, pg 16-17)
Du	/] [r 🗶	18 Jam	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15) Licensing Official Da Dima