
Capacity 153



FEB | 2707

TATE DEPARTMENT OF HEALTH

Facility Inspection

Purpose Penewal MYT Cap	acity 153		12-2-20-20-20-20-20-20-20-20-20-20-20-2	100	00000000000000000000000000000000000000
All Items In Red Are Critical In Out COS N/A Qualified director present	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities		Out D D	COS	
Proper staff to child ratio present Room and playground capacity met Center capacity met License/complaint visible	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair	W.			
Certified food manager Sanitation Approved	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded	DAME.			
Vector control maintained Water system approved and inactioning	Telephone on premises, available, and functioning	W W	· _		O
Waste water system approved and functioning Food service approved	Electrical outlets protected Large appliances located properly Sinks and toilets working properly	Y.			B
Possible Monetary Penalty Monetary Penalty 1	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet			8	
2.	nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good				K
	working order Exits unobstructed	B			
5	Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and	K			
9 3/4 (6) Age/Child/Staff NCG	in good working order		' 🗆		
2. 3yrs (D) CG3	First aid kits stocked and easily accessible Playground area clean, shaded, well	E/	О		О
The state of the s	drained and equipped and fence in good repair	b'		О	О
	Playground equipment meets standards	0			
	Pool area clean, fenced, and adequately maintained				b
	Diaper changing stations adequate in number and the fully supplied nher				D

Form No. 287





MISSISSIPPI STATE DEPARTMENT OF HEALTH

District_5	Sunshine Learning Center 5035 Highway 80 Fast Pearl MS 39208 Date 4.10.81
Name	Lic # 0617 601.939.0854 No
Address	Capacity 153 Center/Organization/Individual
Purpose Henewat	Mid Year Inspetin Director Christie Capeland
Mileage Start	Mileage End
County Kankin	Telephone No.
Time In 9:00	Time Out // // Total Time
Ms. Cape land Was to Conduc	
Sunny todays	visit. Facility, NO Critical Violation
	"Class I and II violations may result in a monetary penalty. Repeated violations may result in the doubling of a monetary penalty, suspension, or revocation of the license."
10.0/	LO- Licensing Official COS-Corrected on Site TA-Technical Assistance POC-Plan of Correction LOS-Letter of Suitability
enter Director Designed India	actual Children Room Supplied Williams

Mississippi State Department of Health

Sunshine Learning Center ility Inspection Results

5635 Highway 80 Fab | Pearl MS 39268 Lic # 0617 601.939.0854 Capacity 153

Date 4 / 4 21

No Critical Vo Chserved on -	bolations boday's					AND SCHEDURE	
Visit 18						FEB 1 2 2021	
			12. 2. 2. 2. 2.				
200 A 100 A					F.11		
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection	92010 Permit No 92015 Permit 1 92011 Permit 2 92012 Permit 3 92013 Permit 4	Charge \$30.00 \$100.00 \$150.00 \$200.00		d Manager		Licence Number	7
92090 Restaurant Training Permit Date	Environmentalist Co		mentalist Sign	asorg .	4XX		

White Copy - Pacifity

Yellow Copy - PIMS/ Pink Copy- Environmentalist

Please Remit within 10 days to:

sure Playeround Checklist Sunshine Learning Center Pearl MS 39208 Inspection Date & 1081 Lic # 0617 601.939.0854 2 2021 Capacity 153 NO NA Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 48) In good repair. I. with no gaps? (Rule 1.11.9 (8), pg 48) 2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48) 2. Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8) 3. AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47) 4. No standing water present on playground or in/on playground equipment or walkways? 5. (CPSC 2.4.2.2-5, pg 10) Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36) 6. Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15) All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing 8. twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47) Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15) Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40) 10. If swings are present, are S-books in good repair? If not, state deficiency II. (CPSC 3.2, pg13) If slide is present, is exit height/exit zone adequate? If not, state deficiency 12. (CPSC5.3.6.4-5 pgs 34-35) Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15) 13. Is age-appropriate equipment being used? If not, state which pieces are inappropriate 14. (Rule 1.10.2, pg 36) Is playground area clean & free of hazards? If not, state deficiency. 15. (Rule 1.11.11 (1), pg 49) 16. Is adequate shade present on the playground? (CPSC 2.1.1. pg 5) 17. Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)

Is wood smooth? Documentation provided that wood has been properly treated. (CPSC

Licensing Official

Director