

## MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

County Carle	Date 10 22 18
Facility Name Manuel Gioro Head	Start License Number 2734
Purpose Renewal	Capacity_169
All Items In Red Are Critical  Qualified director present  Proper staff to child ratio present	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities  In Out COS N/A  U U U U U U U U U U U U U U U U U U U
Room and playground capacity met  Center capacity met  License/complaint visible	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair
Certified food manager	Lighting approved  Heating/cooling approved  Ventilation adequate  Glass approved and shielded  Telephone on premises, available,
Waste water system approved and functioning	and functioning  Electrical outlets protected  Large appliances located properly  Sinks and toilets working properly
Possible Monetary Penalty  Monetary Penalty  \$	Hot water at all sinks, not to exceed 120°  Children barred from kitchen  Vending machine snacks meet
2\$	nutritional guidelines, if present  Exits, doors and fastening devices single action approved and in good
4.       \$         5.       \$	working order  Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers
Age/Child/Staff Name 1.	and thermometers placed properly and in good working order
2. 3.	First aid kits stocked and easily accessible   Playground area clean, shaded, well
4.	drained and equipped and fence in good repair  Playground equipment meets standards
5. 6.	Playground equipment meets standards
Center Director/Individual	Diaper changing stations adequate in number and each fully supplied (number)  Child Care Representative
White Copy - Facility File Yellow Copy - Facility Operator	12-10-08 Form No. 281



District V	10/22/10
District_V\	Date 10 27 18
Name Manuel Gogo Head Start License No. 12001H	1-2736
Address 207 Chesnut Street, Quitman Center/Organization/Individual	
Purpose Renowal Director Chris Evo	ins
Mileage Start Mileage End	
County Clarke Telephone No. 601-776-	-6010
Time In 12:00 Total Time_	
Findings/Comments Upon arrival, Chris Evans - Director - those were no children today due to a teacher	informed me that workshop day.
a survey was given to Chris Evans.	
Please submit application & fu online at h	ealthyms com by
Please submit fire form 333 & 2 wx cycle of n	nenus to
Fax 601-425-1080	
email jessica. heap @ msdh. ms. gov	
* a business card was given to Chris Evans	with contact
information. A	
Center Director/Designee/Individual  Child/Care Representative	White Copy - Facility File Yellow Copy - Operator



## Child Care Program Review

Facility Name Manual Gob HS	License No	2736	Date 10 22 16	
Yes No N/A  1.				
Comments/Recommendations	1			
Pass – License to be issued: Regular Proba  Fail Follow-up within days	MA	Child Care	Nap Representative	

## **Food Service Facility Inspection Results**

PIMS ID	Facility Name, Address Manuel	Copp Head Stout Date
- 11.10	207 Che	Court G
	- Qui	man MS 39355 10/22/18
CRITICAL	/IOLATIONS	CORRECTION PLAN AND SCHEDULE
No deficiencie	j Obsined	
□ 92020 Scheduled □ 92030 Followup □ 92040 Complaint □ 92050 Consultation	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00	Tamara May Certified Manager  Licence Number
☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training	92013 Permit 4 \$200.00	Facility Signature
Permit Date  Please Remit within 10 days t	Environmentalist Code o:	White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist

## Child Care Licensure Playground Checklist

Center Name	Manuel Goff Head Start Inspection Date 10/22/18
YES NO N/A	
	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
4 0 0	2 entrances/exits, with one being remote from the building? (Rule 1 11 9 (8), pg 48)
Z a a	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
Q 0 0	4. AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
200	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
<u>d</u> 0 0 (	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
Z = = 8	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
009	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC . 3.4, 3.5, pg 15)
	0. Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
0 0 2 1	If swings are present, are S-hooks in good repair? If not, state deficiency  (CPSC 3.2, pg13)
Q 0 0 11	
	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
Q 0 0 14	Is age-appropriate equipment being used? If not, state which pieces are inappropriate  (Rule 1.10.2, pg 36)
<u> </u>	
<b>a</b> a a 17	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
0 18	
Director	Licensing Official Ima 19