

## MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

| County  | Date 2 11 2020  |         |  |  |  |  |  |
|---|---|---------|--|--|--|--|--|
| Facility Name Angie's Child Devel. Cottr. License Number 3990   |   |         |  |  |  |  |  |
| Purpose Mid-yan Ca  | pacity_30   |         |  |  |  |  |  |
| All Items In Red Are Critical  Qualified director present  In Out COS N/A   | Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities | N/A     |  |  |  |  |  |
| Proper staff to child ratio present Room and playground capacity met Center capacity met License/complaint visible Certified food manager | Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair  |         |  |  |  |  |  |
| Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning                   | Heating/cooling approved  Ventilation adequate Glass approved and shielded Telephone on premises, available, and functioning              |         |  |  |  |  |  |
| Waste water system approved and functioning   | Electrical outlets protected  Large appliances located properly  Sinks and toilets working properly                                       |         |  |  |  |  |  |
| Possible Monetary Penalty  Monetary Penalty  1  | Hot water at all sinks, not to exceed 120°  |         |  |  |  |  |  |
| 2\$   | Vending machine snacks meet nutritional guidelines, if present  Exits, doors and fastening devices single action approved and in good     | N       |  |  |  |  |  |
| 4\$   | working order   |         |  |  |  |  |  |
| 5\$Age/Child/Staff Name   | Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and            |         |  |  |  |  |  |
| 1. 4 yro -4   | in good working order  First aid kits stocked and easily accessible   |         |  |  |  |  |  |
| 2. 2 yrs7<br>3. 3 yrs -8  | Playground area clean, shaded, well drained and equipped and fence in good repair   |         |  |  |  |  |  |
| 4. 4 yro 1.   | Playground equipment meets standards  |         |  |  |  |  |  |
| 6.  | Pool area clean, fenced, and adequately maintained  |         |  |  |  |  |  |
| Center Director/Individual  | Diaper changing stations adequate in number and each fully supplied (number)  Child Care Representative                                   | ny -    |  |  |  |  |  |
| White Copy - Facility File Yellow Copy - Facility Operator  | 2-10-08 Form  | No. 281 |  |  |  |  |  |



## Child Care Encounter

|   | Child Care Encounter  | Date 2 11 2020                                       |
|---|---|--|
| District VIII   |   | Date 2 11 WW   |
| NameAddress   | — Angie's Child Development Center  1603 Susie B. Ruffin, Laurel, MS 39440  601-651-2900 Lic. No.: 34C3PFA-3990 |  |
| Purpose Mid-ylar  | Director: Angela Carmichael   |  |
| Mileage Start   | Mileage End   |  |
| County Yorks  | Telephone No  |  |
| Time In 10:00   | Time Out Total Time   | ^  |
| Findings/Comments A Swwa  | y was given to Ms.  | Angil.   |
| Damage - due to<br>is being repaired.<br>Until permanent<br>will notify licer | tornado in December. Temporary bencing was bencing can be comple solng Official when jok                        | to fence of put up ted. Facility is complete.        |
|   |   |  |
|   |   |  |
|   |   |  |
|   |   |  |
|   |   |  |
|   | 1   |  |
| Center Director/Designee/Individual   | Child Care Representative   | White Copy - Facility File<br>Yellow Copy - Operator |
| Mississippi State Department of Health  | Revised 6-24-09   | Form No. 287   |

## Food Service Facility Inspection Results

Angie's Child Development Center 1603 Susie B. Ruffin, Laurel, MS 39440 Facility Name PIMS ID 601-651-2900 Lic. No.: 34C3PFA-3990 11/2020 Director: Angela Carmichael CORRECTION PLAN AND SCHEDULE **CRITICAL VIOLATIONS** No deficiencies observed lummu Array Cormichal Licence Number Certified Manager 92010 Permit No Charge 92020 Scheduled \$30.00 ☐ 92015 Permit 1 92030 Followup \$100.00 ☐ 92011 Permit 2 ☐ 92040 Complaint 92012 Permit 3 \$150.00 ☐ 92050 Consultation 92013 Permit 4 \$200.00 ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection Facility Signature ☐ 92090 Restaurant Training Environmentalist Signature Environmentalist Code Permit Date White Copy - Facility Please Remit within 10 days to: Yellow Copy - PIMS Pink Copy- Environmentalist

## Child Care Licensure Playground Checklist

| Cent | er N | ame. | Ana | jus Child Development Contr. Inspection Date 2/11/2020   |
|------|------|------|-----|--|
| YES  | NO   | N/A  | 1.  | Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 48) In good repair,   |
| A    |      |      | 2.  | 2 entrances/exits, with one being remote from the building? (Nate 1.11.) (0), P8. 10)  |
|      |      | A    | 3.  | Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)  |
| N    |      |      | 4.  | AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)  |
| A    |      |      | 5.  | No standing water present on playground or in/on playground equipment or walkways?   |
| Z    |      | П    | 6.  | (CPSC 2.4.2.2-5, pg 10)  Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)   |
| Z    |      |      | 7.  | it must walking surface? (no trip liazards) (cr bo s.o, ps - /   |
| . ]  | Z    |      | 8.  | All bolts on equipment & fence <2 threads beyond the nut; Alc an ootes and sold and  |
| J    |      | A    | 9.  | Tree limbs at least 7ft. above play surfaces? Is lence nee of brash over grant and the state of brash over g |
| ]    |      | A    | 10. | 3.4, 3.5, pg 15) Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)  |
| ]    |      | Ä    | 11. | If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)   |
| ]    |      | A    | 12. | If slide is present, is exit height/exit zone adequate? If not, state deficiency  (CPSC 5. 3. 6.4-5 pgs 34-35)   |
| 1    | П    | V    | 13. | Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)   |
| X    |      |      | 14. | Are spring rockers a minimum of 6 to appropriate  Is age-appropriate equipment being used? If not, state which pieces are inappropriate  (Rule 1.10.2, pg 36)  |
| ]    |      |      | 15. | Is playground area clean & free of hazards? If not, state deficiency.  (Rule 1.11.11 (1), pg 49)   |
| ¥    | П    | П    | 16. | Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)  |
| X    |      |      | 17. | Section located at least 6" heneath the surface: (Nate 1.10.2 (2), 18 0)   |
| +    |      |      | 18. | Are concrete footings located at loady of the location provided that wood has been properly treated. (CPSC 2.5.5)  Licensing Official  |
| reci | br_  |      | V   |  |