



MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child

in

County Harrison

FIRST BAPTIST PRESCHOOL LONG BEACH

300 N CLEVELAND AVE

LONG BEACH, MS 39560

228-864-2589 Lic. No.: 4608

Director: RUBY BLACKWELL

5-30-18

Facility Name _____

iber _____

Purpose mid-yearCapacity 145**All Items In Red Are Critical**

Qualified director present

Proper staff to child ratio present

Room and playground capacity met

Center capacity met

License/complaint visible

Certified food manager

In Out COS N/A

☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐**Sanitation Approved**

Garbage and garbage bins maintained

Vector control maintained

Water system approved and functioning

Waste water system approved

and functioning

Food service approved

☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐**Possible Monetary Penalty**

Monetary Penalty

1. _____ \$ _____

2. ~~See Form 277~~ \$ _____

3. _____ \$ _____

4. _____ \$ _____

5. _____ \$ _____

Age/Child/Staff Name

1. _____

2. See Form 277

3. _____

4. _____

5. _____

6. _____

7. _____

Other Items - Must be corrected

Children's belongings separated/stored

Evacuation plans posted

Menus posted and served

Plan of activities

In Out COS N/A

☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐☒ ☐ ☐ ☐**Building and Grounds**

Walls, ceilings, floors, toys, equipment

clean and in good repair

☒ ☐ ☐ ☐

Lighting approved

☒ ☐ ☐ ☐

Heating/cooling approved

☒ ☐ ☐ ☐

Ventilation adequate

☒ ☐ ☐ ☐

Glass approved and shielded

☒ ☐ ☐ ☐

Telephone on premises, available,

and functioning

☒ ☐ ☐ ☐

Electrical outlets protected

☒ ☐ ☐ ☐

Large appliances located properly

☒ ☐ ☐ ☐

Sinks and toilets working properly

☒ ☐ ☐ ☐

Hot water at all sinks, not to

exceed 120°

☒ ☐ ☐ ☐

Children barred from kitchen

☒ ☐ ☐ ☐

Vending machine snacks meet

nutritional guidelines, if present

☐ ☐ ☐ ☒

Exits, doors and fastening devices

single action approved and in good

working order

☒ ☐ ☐ ☐

Exits unobstructed

☒ ☐ ☐ ☐

Required smoke detectors, carbon

monoxide monitors, fire extinguishers

and thermometers placed properly and

in good working order

☒ ☐ ☐ ☐

First aid kits stocked and easily accessible

☒ ☐ ☐ ☐

Playground area clean, shaded, well

drained and equipped and fence in good

repair

☒ ☐ ☐ ☐

Playground equipment meets standards

☒ ☐ ☐ ☐

Pool area clean, fenced, and adequately

maintained

☐ ☐ ☐ ☒

Diaper changing stations adequate in

number and each fully supplied

(number _____)

☒ ☐ ☐ ☐

Center Director/Individual

Child Care Representative

White Copy - Facility File

Yellow Copy - Facility Operator

Mississippi State Department of Health

12-10-08

Form No. 281



MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Encounter

District IX

Date 5-30-18

Name	FIRST BAPTIST PRESCHOOL LONG BEACH	
Address	300 N CLEVELAND AVE LONG BEACH, MS 39560	
Purpose	228-864-2589 Lic. No.: 4608 Director: RUBY BLACKWELL	
Mileage Start	Mileage End	
County	Telephone No.	
Time In	Time Out	Total Time

Findings/Comments NO violations cited. All in compliance for mid-year inspection.

A survey and business card were provided.

[Signature]
Center Director/Designee/Individual

[Signature]
Child Care Representative

White Copy - Facility File
Yellow Copy - Operator


Food Service Facility Inspection Results

FIRST BAPTIST PRESCHOOL LONG BEACH
300 N CLEVELAND AVE
LONG BEACH, MS 39560
228-864-2589 Lic. No.: 4608
Director: RUBY BLACKWELL

PIMS ID	Facility Name, Address	Date
		5-30-18

CRITICAL VIOLATIONS



CORRECTION PLAN AND SCHEDULE

no critical violations	
------------------------	--

<input type="checkbox"/> 92020 Scheduled <input type="checkbox"/> 92030 Followup <input type="checkbox"/> 92040 Complaint <input type="checkbox"/> 92050 Consultation <input type="checkbox"/> 92070 Plan Review/Const. <input type="checkbox"/> 92080 No Inspection <input type="checkbox"/> 92090 Restaurant Training	<input type="checkbox"/> 92010 Permit No Charge <input type="checkbox"/> 92015 Permit 1 \$30.00 <input type="checkbox"/> 92011 Permit 2 \$100.00 <input type="checkbox"/> 92012 Permit 3 \$150.00 <input type="checkbox"/> 92013 Permit 4 \$200.00
Permit Date	Environmental Code
Please Remit within 10 days to:	

Ruthie Williams
Certified Manager

ServSafe
Licence Number
exp. 2020

Facility Signature	
Environmental Signature	

White Copy - Facility
Yellow Copy - PIMS
Pink Copy- Environmentalist

Child Care Licensure Playground Checklist

Center Name Fbc Preschool

Inspection Date 5-30-18

YES ☒ NO ☐ N/A ☐

1. ☒ ☐ ☐ Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
2. ☒ ☐ ☐ 2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
3. ☒ ☐ ☐ Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
4. ☒ ☐ ☐ AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
5. ☒ ☐ ☐ No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
6. ☒ ☐ ☐ Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
7. ☒ ☐ ☐ Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
8. ☒ ☐ ☐ All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
9. ☐ ☐ ☒ Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
10. ☒ ☐ ☐ Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
11. ☐ ☐ ☒ If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)
12. ☒ ☐ ☐ If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC 5.3.6.4-5 pgs 34-35)
13. ☐ ☐ ☒ Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
14. ☒ ☐ ☐ Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 36)
15. ☒ ☐ ☐ Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49)
16. ☒ ☐ ☐ Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
17. ☒ ☐ ☐ Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
18. ☐ ☐ ☒ Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)

Director

Janita J. Gentry

Licensing Official

Amanda K. Smith