

## MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

County Clifton Preston Head Start 101 Center Avenue, Sumrall, MS	39429 = 3 · 18 · 19			*	
Facility Name	3993				
Purpose Six Month.	many50	8			
All Items In Red Are Critical  Qualified director present  Proper staff to child ratio present	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities		Out	COS	<b>N/A</b>
Qualified director present  Proper staff to child ratio present  Room and playground capacity met  Center capacity met  License/complaint visible  Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair				
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning Waste water system approved	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available, and functioning	papp p			
and functioning Food service approved  Possible Monetary Penalty	Electrical outlets protected  Large appliances located properly  Sinks and toilets working properly	AAA AAA			
Monetary Penalty  1	Hot water at all sinks, not to exceed 120° Children barred from kitchen				
2\$	Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good				
4.       \$	working order  Exits unobstructed  Required smoke detectors, carbon				
Age/Child/Staff Name  1.	monoxide monitors, fire extinguishers and thermometers placed properly and in good working order				
2. See 2nd Experience	First aid kits stocked and easily accessibe Playground area clean, shaded, well	le 🗌			
3. See 2 Encounter 4.	drained and equipped and fence in good repair				
5.	Playground equipment meets standards	P			
6	Pool area clean, fenced, and adequately maintained				
Center Director/Individual Levenue Dowerson  White Copy - Facility File Yellow Copy - Facility Operator	Diaper changing stations adequate in number and each fully supplied (number)  Child Care Representative	ha	D		Ena

Mississippi State Department of Health

12-10-08

Form No. 281



## **Child Care Encounter**

		Date 3.18.19
ddress	Clifton Preston Head Start  101 Center Avenue, Sumrall, MS 39429  601-758-3297 Lic. No.: 37CCIH-3993  Director: SHABORIA SARTIN	
urpose <u>Six Mon4</u>		
	Mileage End	
	Telephone No	
me In 1:40		
urrival no	l'incompliance during ? No deficiencies observe with y. Borness.	
Durvey ca	nd given to director	designee.

Clifton Preston Head Start 101 Center Avenue, Sumrall, MS 39429 601-758-3297 Lic. No.: 37CCIH-3993 Director: SHABORIA SARTIN



Date 3 · 18 · 19

Facility Name		License No	
hoom	lge	Child	Staff
A	3	16	
В	3	9	
	3	12.	
Genter Director/Designee/Individu	ual Child Care Repr	Dennyo resentative	White Copy - Facility File Yellow Copy - Operator

## Food Service Facility Inspection Results

Clifton Preston Head Start

	101 Center Avenue, Sumrall, MS 39429		
PIMS ID	Facili 601-758-3297 Lic. No.: 37CCIH-3993 Director: SHABORIA SARTIN	Ť.	3 · 18 · 19

	Director: Shabokia Sakrik	3.18.19
CRITICAL VIOI	ATIONS	CORRECTION PLAN AND SCHEDULE
No critical vio	3/04.005	Focility issued on letter grade
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00	Certified Manager Licence Number  Facility Signature  Bawen
Permit Date  Please Remit within 10 days to:	Environmentalist Code	Environmentalist Signature  White Copy - Facility Yellow Copy - PIMS
		Pink Copy- Environmentalist

Clifton Preston Head Start

101 Center Avenue, Sumrall, MS 39429 601-758-3297 Lic. No.: 37CCIH-3993

Director: SHABORIA SARTIN

## Child Care Licensure Playground Checklist

				Inspection Date 3.18.19
Cente	er Na	me_		•
YES	NO	N/A	1.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)
			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
P			5.	No standing water present on playground or in/on playground equipment or walkways?  (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
æ			6.	Toys & equipment in good repair? (none broken/deteriorating) (Nate 1.10.2 (2), PS 10)
P			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
P			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
P			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC
A			10.	Are use zones adequate? If not, where are they inadequate? (CFSC 5.5.9, pg 41)
			11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14; 2.5.2, pg 1 & 5.3.8.1, pg 37)
<u></u>			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
			• 13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate  (Rule 1.10.2, pg 46)
				& CPSC 2.2.6, pg 6)
Þ			15.	Is playground area clean & free of hazards? If not, state deficiency.  (Rule 1.11.11 (1), pg 61)
		П	16.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 & CPSC 3.6, pg 16-17)
		1	18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
Dire	ctor	<u>Lfe</u>	war	2.5.5, pg 15)  Licensing Official Manocho Romano