

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Facility Inspection

County TUMN Ney	Date_ 4 24 W			
Facility Name Mans All Churan Cent	License Number 200	PFA	-369	9
Purpose Le Month M Cap	pacity 42			
All Items In Red Are Critical Qualified director present Proper staff to child ratio present Room and playground capacity met	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In O	ut COS	N/A
Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair		1 0	
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning Waste water system approved	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,			
and functioning Food service approved	and functioning Electrical outlets protected] [
Possible Monetary Penalty Monetary Penalty	Large appliances located properly Sinks and toilets working properly Hot water at all sinks, not to			
2	exceed 120° Children barred from kitchen Vending machine snacks meet			
3	nutritional guidelines, if present Exits, doors and fastening devices			
4\$	single action approved and in good working order Exits unobstructed			
Age/Child/Staff Name	Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and			
1. IN fants 3 1 CARIGITYER	in good working order		/ · 🗆	
3. LURAR DICULO 2 CARLATTERS	First aid kits stocked and easily accessible Playground area clean, shaded, well	e /] 🗆	
4.	drained and equipped and fence in good repair] 🗆	
5. 6.	Playground equipment meets standards	1] 🗆	
7.	Pool area clean, fenced, and adequately maintained] 🗆	
Θ_{-0} Ω_{-}	Diaper changing stations adequate in number and each ully supplied (number)			
Center Director/Individual Clouds Tomas	_ Child Care Representative	Ma	Un	ط
White Copy - Facility File Yellow Copy - Facility Operator Mississippi State Department of Health 12-10	-08	,	Form No.	. 281

Form No. 281



MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Encounter	11/10/11/2012
District O	Date 4/24/2018
Name Noahy April Christian Center License No. 27 CCOT	A-3699
Address 90' July St., INAMY 38754	11 0011
Purpose UMINTH Center/Organization/Individual Director_DelOUS TAN	NER
Mileage Start Mileage End	
County TUMPNEUS Telephone No. (ULL) 902-2	160
Time In 2555 m Time Out 200 pm Total Time	
Findings/Comments The pulpose FOR WIT IT FOR A SIX-MONTH	Dispection.
Subchapter 11: Buildings & Grounds	
Pula I II Pologo pologo pologo de como	
Finding: LO Observed the Horring beneath the Purt	ropely Installed
DONAN I ACIUM TE to OFFICE A LONG TO THE TOTAL	eoom Wifet
Plan of correction	O VOTE
Per. D. Tarrel, director she has parteen particularly	N FRIEND OF
Church and they will be completing Repaires by Arign	
Stored I'm STY WILL CONTINUE REJOURS IT THE VENOUS	hons have not
bean completed by fright.	
KULE . 11. 1 (12) STATES IN PART, WALL Shall be kept Cite	2011/11/11/11
JULY Wall Corelines. (hupped neut hanked alader of ha	les.
Though to observed it intolo The behind the mi	HEBEDN the
	ilet.
Plan of Coepection	
See #12 plan of coelection under line 1.1.1(8)	
Pula III IIIS) states to may 111 from 1	
sewiced on an annual basis. All file extinguished	u smube
produces a poselved the extingiunal outdated, I	werel in the
therity passed the flu town #333.	
Telores Farner Nara (ones	hite Copy - Facility File llow Copy - Operator
Center Director/Designee/Individual Child Care Representative Ye	now Copy - Operator



Child Care Encounter

Facility Name Noahy April Chlistian Center License No. 27 Center 349 White Copy - Facility File Yellow Copy - Operator Center Director/Designee stative

Food Service Facility Inspection Results

DIA (C. ID.	100	His of top me	
PIMS ID Fa	cility Name, Address 407	ran Centel 38 754	Date 4124/2018
CRITICAL VIO	LATIONS	CORRECTION PLAN A	ND SCHEDULE
M Citical Observed.		Mot compla	ince)
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training Permit Date Please Remit within 10 days to:	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00 Environmentalist Code	Facility Signature Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	Tumwher Licence Number April 2022

Child Care Licensure Playground Checklist

Center Name Mahu All Chritian CENTEL Inspection Date 4/24/2018				
	S NO			' /
			1.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
6			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
Ø			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)
D			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
Þ			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
Ø			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
\not			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
Ø/			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
1			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
ø			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
		P	11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14;
/				2.5.2, pg 1 & 5.3.8.1, pg 37)
			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
		Ø	13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
Z			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 46)
	1			& CPSC 2.2.6, pg 6)
			15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 61)
Ø,			16.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
P			17. /	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 & CPSC 3.6, pg 16-17)
		Z \	18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
Direc	tor L)el	ous	Janu Licensing Official Ward Janus