Brushy Creek Head Start Center 617 North Jackson Street Crystal Springs, MS 39059 (601) 892-3826 Lic# 2456 Capacity: 150



Facility Inspection

County Copiah	Date/	19.21	
Facility Name	License Numb	er	
Purpose Benewal	Capacity		
All Items In Red Are Critical In Out	Other Items - Must be Children's belongings sepa Evacuation plans posted Menus posted and served Plan of activities		COS N/A
Qualified director present Proper staff to child ratio present Room and playground capacity met Center capacity met	Building and Grounds Walls, ceilings, floors, toy- clean and in good repair	s, equipment	
License/complaint visible Certified food manager Sanitation Approved	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shield	ed	
Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Telephone on premises, av and functioning	ailable,	
Waste water system approved and functioning Food service approved	Electrical outlets protected Large appliances located p Sinks and toilets working	roperly	
Possible Monetary Penalty Mone S	Hot water at all sinks, not exceed 120° Children barred from kitch Vending machine snacks recognitions.	nen 💮	
2	nutritional guidelines, if pa Exits, doors and fastening single action approved and	resent	
3,\$	working order	i ili good	
4. \$ 5. \$	Exits unobstructed Required smoke detectors monoxide monitors, fire e	xtinguishers	
Age/Child/Staff Name	and thermometers placed in good working order	property and	
No Children Dresel	First aid kits stocked and o		
2. [Virual fearning	Playground area clean, sha drained and equipped and repair		
4.	Playground equipment me	ets standards	
6.	Pool area clean, fenced, an maintained	nd adequately	
7.	Diaper changing stations a number and each fully sup (number)		
Center Director/Individual White Copy - Facility File Yellow Copy - Facil Mississippi State Department of Health	Child Care Represently Operator	entative A Agrae	m No. 281



Mississippi State Department of Health

MISSISSIPPI STATE DEPARTMENT OF HEALTH

District 5	Brushy Creek Head Start Center 617 North Jackson Street Crystal Springs, MS	ounter	Date 1.19.21
Name	39059 (601) 892-3826 Lic# 2456 Capacity: 150	icense No	
Address		zation/Individual	
Purpose Rangua	2/	Director Arce	DAVIS
Mileage Start	M	lileage End	
County CODICA	Te Te	elephone No	
Time In 12:30	Time Out	Total Time	· · · · · · · · · · · · · · · · · · ·
Findings/Comments = director VISIT Was After a Violations Needed do Anhact h	ARRIVED At the JOCA TOUR OF the Juring this cuments:	Renewal I	met uf reason flu forby inspection. Crifical aspection.
	"Class Land I	l violations may	
	result in a mo	onetary penalty.	
	Repeated violat	tions may result in	
	the doubling of a suspension, or revo	monetary penalty, ocation of the license."	
Center Director/Designe	ee/Individual enjid gare Re	epresentative	White Copy - Facility File Yellow Copy - Operator
Mississippi State Departme	ent of Health	Revised 6-24-09	Form No. 287

Brushy Creek Head Start Center 617 North Jackson Street Crystal Springs, MS 39059 (601) 892-3826 Lic# 2456 Capacity: 150



Program Review

ite 🔟	11	7	id	
l	te 🦼	te /r/	te / 19	te 1, 1918

Ves. No. N/A
Pass License to be issued: □ Regular □ Probational □ Restricted □ Fail □ Follow-up within days □ Director □ Designee Child Care Representative

Mississippi State Department of Health White Copy - Facility File

Yellow Copy - Operator

Revised 12-19-13

Brushy Creek Head Start Center 617 North Jackson Street Crystal Springs, MS 39059 (601) 892-3826 Lic# 2456

lity Inspection Results

(601) 892-3826 Lic# Capacity: 150				1.19.21	
CRITICAL VIOLATIONS			CORRECTION P.	LAN AND	SCHEDULE
No critical Via during Benev	olatims Natinspret				
☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training	92010 Permit No Charge 92015 Permit 1	00.00	Certified Manager Facility Signature Environmentalist Signature	Sarp Fill	Sexp. 1.29.21 cence Number
Please Remit within 10 days to:			White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalis	st C)

Brushy Creek Head Start Center 617 North Jackson Street Crystal Springs, MS 39059 (601) 892-3826 Lic# 2456

Capacity: 150

ensure Playground Checklist

Inspection Date 1.19.31
than 3 1/2" from surface. (Rule 1.11.9 (8), pg 48) In good repair,

YES	NO	N/A	3. 17.	
			Į.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
P			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
E			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
d	Π,		5.	No standing water present on playground or in/on playground equipment or walkways?
1			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
H			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
and a			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC
M			10.	3.4, 3.5, pg 15) Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
			11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)
Ø			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5. 3.6.4-5 pgs 34-35)
			13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 36)
9			15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49,
			16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
A.			į7.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
d			18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
Direct	or 👱	Su	(see	Licensing Official _