

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Facility Inspection

County Actor 15	Date 3.10.21			
Facility Name Hansel & Gretel	License Number_056	0	-	
Purpose Mid- Year	Capacity/00			
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	Children's belongings separated/stored Evacuation plans posted	In Out	COS	N/A
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair			
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,			
Waste water system approved and functioning Food service approved	and functioning Electrical outlets protected Large appliances located properly			
Possible Monetary Penalty 1 Monetary Penalty \$	Sinks and toilets working properly Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet			
3	nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good			
4	working order Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers			
1. 248/11/Caregiver 1	and thermometers placed properly and in good working order First aid kits stocked and easily accessible			
3. 3. 4yR/18 N 113 € 4	Playground area clean, shaded, well drained and equipped and fence in good repair			
5. Infant /7 11 11 (0 & 7	Playground equipment meets standards			
6	Pool area clean, fenced, and adequately maintained			
Center Director/Individual Cally Key	Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative	hong	San	diA
White Copy - Facility File Yellow Copy - Facility Operator Mississippi State Department of Health	12-10-08	For	m No.	281



Child Care Encounter

District	Date 2 · 10 · 21
Name Hansel & Gretel	
Address 180 B. Sgt. Prentis	5 Drive, Notchez MS 39120
Purpose Mid-Year	Director C. King (D. Designee
Mileage Start	Mileage End
County Adams	Telephone No. 40.442.7774
	45 Total Time
With D. Designee C	facility and met C. King stated purpose
No critical violation:	s@thetime of visit.
Class I & II violations penalty. Repeated violated violat	may result in a monetary tions may result in the penalty's Supension
Thanks for all you do safe!	and continue to Keep
A green survey card	was given to didesignee
* Tummy Safe Expire	5 φ·22·2021
Colly King Sulface/Individual Child Can	White Copy - Facility File Yellow Copy - Operator

Food Service Facility Inspection Results

PIMS ID Facility Name, Address Homsel & Gretel Date 180 B. Sgt. Prentiss Notchez MS 3.10.21		
CRITICAL VIOLATIONS	CORRECTION PLAN AND SCHEDULE	
No critical violation at the time of	5	
ViSit.	A"Issued	
□ 92020 Scheduled □ 92010 Permit No Charge □ 92030 Followup □ 92015 Permit 1 \$30.00 □ 92040 Complaint □ 92011 Permit 2 \$100.00 □ 92050 Consultation □ 92012 Permit 3 \$150.00 □ 92070 Plan Review/Const. □ 92013 Permit 4 \$200.00 □ 92080 No Inspection □ 92090 Restaurant Training Permit Date Environmentalist Code Please Remit within 10 days to:	Certified Manager Licence Number Expires Cartified Manager Licence Number Expires Facility Signature Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	

#0560

Child Care Licensure Playground Checklist

Center Name	hed ? Grete Inspection Date 3.10.21
YES NO NA	
Ø 0 0 1.	Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
□ □ 2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8). pg 60)
☐ ☐ 3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 7.4.2, pg 9-10 & 4.3)
0 0 4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
<u>d</u> 0 0 5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
D 0 0 6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
, of 0 0 7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
1 0 0 8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
Z = 9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
0 0 0 11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14;
0 0 12.	2.5.2, pg 1 & 5.3.8.1, po 37)
12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency
O O Ø 13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
D 0 14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rade 1.10.2, pg 46)
Z = 1 16	& CPSC 2.2.6. pg 6)
<u> </u>	Is playground area clean & free of hazards? If not, state deficiency.
D D 16.	Is adequate challenged in the second of the
Ø □ □ 17.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 & CPSC 3.6, pg 16-17)
Ø □ □ 18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
Director Cally	Licensing Official & Moh Smile
	The state of the s