

## MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

County Washington					Date 10/25/20	17			
Facility Name LiP Dar	lings				License Number_76C3	BPF	4-	55	18
Purpose 6 months ins	pection	/TA		Cap	acity30				
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	In Out	COS	N/A		Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities		Out	cos	<b>N/A</b>
Room and playground capacity met Center capacity met License/complaint visible Certified food manager					Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair	4			
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning				]	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,				
Waste water system approved and functioning					and functioning				
Food service approved  Possible Monetary Penalty	Monetai	y Ponal	tv/		Electrical outlets protected Large appliances located properly Sinks and toilets working properly Hot water at all sinks, not to				
1	\$	y renai	Ly		exceed 120°  Children barred from kitchen				
3,	\$ \$				Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices				
4.					single action approved and in good working order				
5	\$		_		Exits unobstructed Required smoke detectors, carbon				
	a Barb		heryl <del>Xidic</del>	0	monoxide monitors, fire extinguishers and thermometers placed properly and the good working order				
	1c Mill	ian		-  ĭ	First aid kits stocked and easily accessib	le 🔽			
3 <sub>.1</sub> 4 <sub></sub>					Playground area clean, shaded, well drained and equipped and fence in good repair				
5.				-	Playground equipment meets standards				
7.					Pool area clean, fenced, and adequately maintained				
	2	90			Diaper changing stations adequate in number and each fully supplied (number)	1 11		另	
Center Director/Individual Syn Ban Child Care Representative Jewesu Liggin					1gin				
White Copy - Facility File Yellow C Mississippi State Department of Heal	opy - Facilit th	y Operai		12-10	)-08		Fo	orm No	. 281



## **Child Care Encounter**

District III	Cilia Care Lifeodittei	10/25/2019
District	<del></del>	Date 10 25 2017
Name Lil Darlings L	earning Center License No. 76 C3PF	A-5578
Address 714 7th Str		
Purpose 6 months insp	ection/T.A. Director Lisa McMilli	an
Mileage Start	Mileage End	
county Washington	Telephone No	6-0307
Time In 10:44 a.m.	Time Out 11:46 a.m. Total Time	
Findings/Comments He l Mc Millian.	icensing official met with Sylvice	Barber and Lise
The purpose for technical assistan	this Visit was for a six mon	ths inspection and
(hp-to date) in	1.25.9(2L) states in part, "Jailur munization in each child's record consing official observed during ?	
check that (1)	childes & MSOH DI form had expe	recl.
P.O.C. The facility	word a monetary penalty Sylvia	Bushow will be
responsible for co	intesting parents to get a current A	15DH 121 form Pulled 17
T. A) Sechnicle ass	istand was provided on Rule 1.	25.9(2L)V
	colations may result in a more	tary penalty.
peralty, Suspen	sion, or revocation of the lies	g of a moralary
Form Prairie	Chalcan L	
office# 1662	-332-8/77	
Pax# 662	-378-2620	
Center/Director/Designee/Individual	idual Child Care Representative	White Copy - Facility File Yellow Copy - Operator

## **Food Service Facility Inspection Results**

PIMS ID	Facility Name, Address	irlings Learning Center Date
76C3PFA-5578		Letand, MS 38756 10/25/2017
CRITICAL VI	OLATIONS	CORRECTION PLAN AND SCHEDULE
-observed no	Violations	
		Facility received a grade of "A".
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection	☐ 92010 Permit No Charge ☐ 92015 Permit 1 \$30.00 ☐ 92011 Permit 2 \$100.00 ☐ 92012 Permit 3 \$150.00 ☐ 92013 Permit 4 \$200.00	Sylvia Barber Certified Manager  Licence Number  Exp. 06/10/202
☐ 92090 Restaurant Training		Facility Signature
Permit Date	Environmentalist Code	Environmentalist Signature  January Regulity
Please Remit within 10 days to		White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist

## **Child Care Licensure Playground Checklist**

Cer	iter N	ame ,	Lil	Darlings Learning Center Inspection Date 10/25/17
YES	, NO	N/A		
			1.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
4			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)  No equipment present
			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
			11.	If swings are present, are S-hooks in good repair? If not, state deficiency  (CPSC 3.2, pg 14;
			,	2.5.2, pg 1 & 5.3.8.1, pg 37)
			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency  (CPSC5.3.6.4-5 pgs 34-35)
			13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate  No equipment (Rule 1.10.2, pg 46)
			15.	& CPSC 2.2.6, pg 6) Is playground area clean & free of hazards? If not, state deficiency.
	<i>a</i>			(Rule 1.11.11 (1), pg 61)
the state of the s			16.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 & CPSC 3.6, pg 16-17)
			18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
Direc	tor		yr	Bo Licensing Official Teresa Liggens