

MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection

County Decree	Date (101.005, 21
Facility Name Kunty Kids	License Number_2347
Purpose Mid-year	_ Capacity_87
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,
Waste water system approved and functioning	and functioning
Food service approved Possible Monetary Penalty	Electrical outlets protected Large appliances located properly Sinks and toilets working properly
Monetary Penalty S Monetary Penalty	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet
3.	nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good
4\$	working order
5. S	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers
Age/Child/Staff Name	and thermometers placed properly and in good working order
2. Other December 7 "	First aid kits stocked and easily accessible \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
3. 13 4 4. 000 0 million 15 3	Playground area clean, shaded, well drained and equipped and fence in good repair
5,	Playground equipment meets standards
7.	Pool area clean, fenced, and adequately maintained there to marked the pool of the plant of the pool of the plant of the p
Center Director/Individual Melissa Cion	Child Care Representative



District	Date 5.21			
Name Kuntus Krids	License No. 2347			
Address 124-A Pistol Howell Center/Org	Rd Aucedule 39452			
Purpose mid year	Director Ongie mason miss Croom			
Mileage Start	Mileage End			
County Yearge	Telephone No. 601-947- 4774			
Time In Out	Total Time			
Findings/Comments				
CR larens 1215 in complea				
Staffis 1213 & As in Ce	mpliane.			
Buildey- No Vivealion Oberve				
Playground - No Violation Observe				
- Tale of the control				
Elden 'A'				
The same of	al a sinth Pa			
The pool was damaged in Durricane along with fonce it in being repaired.				
				
Melissa Com	White Copy - Facility File Yellow Copy - Operator			

Food Service Facility Inspection Results

PIMS ID	Facility Name, Address		Date	
2347	Kunly Kust	A.	2-521	
CRITICAL VIOLATIONS		CORRECTION PLAN ANI	CORRECTION PLAN AND SCHEDULE	
		Mo Violación Deserve	Temny Solo	
☐ 92020 Scheduled ☐ 92030 Followup ☐ 92040 Complaint ☐ 92050 Consultation ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection ☐ 92090 Restaurant Training		Certified Manager I	Lorona Number	
Permit Date - 30 - 2 Please Remit within 10 days	Environmentalist Code to:	White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	re	