

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Facility Inspection

County Harrison		Date 3 - 20-18				
Facility Name Nugent Methodist	church cpc	License Number 01 78				
Purpose Mid- Year						
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	t COS N/A	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In No.	Out	COS	N/A
Room and playground capacity met Center capacity met License/complaint visible Certified food manager		Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair				
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning		Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,				
Waste water system approved and functioning Food service approved Possible Monetary Penalty		and functioning Electrical outlets protected Large appliances located properly Sinks and toilets working properly				
· · · · · · · · · · · · · · · · · · ·	ary Penalty	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet				
3. \$		nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good working order				
\$\$		Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers				
ff Name	- 13	and thermometers placed properly and in good working order First aid kits stocked and easily accessible				
olderls.	- 8	Playground area clean, shaded, well drained and equipped and fence in good repair				
older3	5-12	Playground equipment meets standards				
older 45	1935 7 10	Pool area clean, fenced, and adequately maintained				
Center Director/Individual B Auda	Centra	Diaper changing stations adequate in number and each fully supplied (number) Child Care Representative	d.	- gin	. Fai	Lley

Yellow Copy - Facility Operator

White Copy - Facility File Yellow Cop Mississippi State Department of Health

Form No. 287



Child Care Encounter

District 9 Date 3-20-/8	
Name August United Mathodist Church Course No 07X	
Name Trought of the Trought State (10. 0. 0.)	_
Name Nugent United Methodist Churcher License No. 078 Address 13783 John Clark Rd. Center/Organization/Individual	-
Purpose Midycar Director Bronda Anderson	
Mileage Start Mileage End	
County Harrison Telephone No. 228-831-2525	_
Time In 9:15 Time Out Total Time	
Findings/Comments Repor anied, met wat the assistant director.	
Building - no violations observered	_
Playpaind- no realations Observered	_
Staff Records- elu compliance	_
Children's Records-In compliance	
Kitchen- No violations Observered - A	
This center had very clean rooms and knowledgeable staps. The betchen was clean and well organized. The stap was friendly and helpful.	
The director and assistant director are doing a Great Je	sh
to the second se	
	-
Center Director/Designee/Individual White Copy - Facility File Yellow Copy - Operator White Copy - Facility File Yellow Copy - Operator	

Revised 6-24-09

Mississippi State Department of Health

Food Service Facility Inspection Results

The second secon	12102 7 1 01 1 1	Date	
PIMS ID Facility Name, Address	13183 John Clark Rd		
Nugent United Metho	odist Church CDC	3-20-18	
9	CORRECTION PLAN AND SCHEDULE		
No Tielations Observered	CORRECTION PLAN ANI	DSCHEDULE	
□ 92020 Scheduled □ 92010 Permit No Charge □ 92030 Followup □ 92015 Permit 1 \$30.00 □ 92040 Complaint □ 92011 Permit 2 \$100.00 □ 92050 Consultation □ 92012 Permit 3 \$150.00 □ 92070 Plan Review/Const. □ 92013 Permit 4 \$200.00 □ 92080 No Inspection □ 92090 Restaurant Training Permit Date Environmentalist Code Please Remit within 10 days to:	Facility Signature Certified Manager Facility Signature Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	ummy Sa Fe icence Namber -x. 5-14-18	

Child Care Licensure Playground Checklist

Cei	nter N	ame`	1) uo	gent Methodist Church COC Inspection Date 3-20-18
YE:	S/NO	N/A		3
			1.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
b			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
			3,.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
4	P		4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
W			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
Ø	П		7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
R			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
			11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg13)
			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC 5. 3. 6. 4-5 pgs 34-35)
d	P		13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate (Rule 1.10.2, pg 36)
V			15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 49)
td	P		16.	Is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
D			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
		D/	18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5)
Direc	tor <u>(</u>	324	nda	Licensing Official Maly fauley