

MISSISSIPPI STATE DEPARTMENT OF HEALTH
Child Care Facility Inspection

County Properties	Date /2/17/20
Facility Name First Methodist Pre	school License Number # W7D
D. D. D. O. A	Capacity38
All Items In Red Are Critical In Out COS N/A	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted In Out COS N/A
Qualified director present Proper staff to child ratio present	Plan of activities
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded
Water system approved and functioning Waste water system approved and functioning	Telephone on premises, available, and functioning
Food service approved	Electrical outlets protected Large appliances located properly Sinks and toilets working properly
Possible Monetary Penalty Monetary Penalty S	Hot water at all sinks, not to exceed 120° Children barred from kitchen
2\$	Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices
4\$	single action approved and in good working order
5\$	Exits unobstructed Required smoke detectors, carbon monoxide monitors, fire extinguishers
1. Age/Child/Staff Name	and thermometers placed properly and in good working order
2. folus &	First aid kits stocked and easily accessible
4. Three 8	drained and equipped and fence in good repair
5.	Playground equipment meets standards
6	Pool area clean, fenced, and adequately maintained
Domin Marin	Diaper changing stations adequate in number and each fully supplied (number)
White Copy - Facility File Yellow Copy - Facility Operator Mississippi State Department of Health	Child Care Representative Wy Wy Church



MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child	Care	Encounter	ø
Cillia	Care	LIICUUIILEI	

District	Date 12/11/20
Name List Methodist Preschool Licens	e No. 59CDRM-0072.
Address 400 W Church St, BODNEVILLE Center/Organization/Individua	M5 38829
	Patrica Down D.
Mileage Start Mileage End	
County Pulntisa Telephone No.	(102) 728-5773
Time In Time Out	Total Time
Findings/Comments Upon arrival licensur the to complete	e Met with director
Frems received: from #333, men rooster. all confact hours are stays.	complete for all
Kitchem received an A	
Playground has no Violati	ions got this
Class Fand H Vinations may result Physity Repeated Wingtons in Alubling & he penalty Suspension Center Director/Designee/Individual Child Care Representative	Mhite Copy - Facility File Yellow Copy - Operator



Facility Name First Mother License No. #0078 Date 12/17/20

License 140.	Date
Yes No N/A 1.	2)} } ! (4) & (5)}
Comments/Recommendations	7
	, , , , , , , , , , , , , , , , , , ,
Pass — License to be issued: Regular Probational Restricted Fail Follow-up within days Director Designee Child C	Day Harb

Food Service Facility Inspection Results

	PIMS ID	Facility Name, Address	not 1) the or you Prayhall Date
	0072	400 West Church	A Romerillo Ma 10/17/00
101	CRITICAL V	IOLATIONS	CORRECTION PLANAND SCHEDULE
	The solution of the solution o	Diffe it.	CORRECTION PLAN AND SCHEDULE
	92020 Scheduled 92030 Followup 92040 Complaint 92050 Consultation 92070 Plan Review/Const. 92080 No Inspection 92090 Restaurant Training	92010 Permit No Charge 92015 Permit 1 \$30.00 92011 Permit 2 \$100.00 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00	Deliver Dolling Turner Age. Certified Manager Licence Number Facility Signature
	Permit Date Please Remit within 10 days to:	Environmentalist Code	Environmentalist Signature White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist

Child Care Licensure Playground Checklist

Cent	ter N	ame	Fu	Inspection Date 12/17/20
VES	NO	N/A		anopeetion Builte _/ / /
			1.	Playground fence less than 3 ½" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
K			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
		K	3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg 9-10 & 4.3)
		A	4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
Ø		./	5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
		6	6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
K			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
Ø			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
		A	9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
		6	10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
		Ø	11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14;
				2.5.2, pg 1 & 5.3.8.1, pg 37)
		Ø	12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
		6	13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate ———————————————————————————————————
			1.5	& CPSC 2.2.6, pg 6)
4	П	Ш	15.	Is playground area clean & free of hazards? If not, state deficiency. (Rule 1.11.11 (1), pg 61)
Þ Þ			16.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
Þ			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 & CPSC 3.6, pg 16-17)
			18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
Directo	or &	Se	nie	Licensing Official Mary Hampton, HPSS