

# **Child Care Facility Inspection Report**

SHERRY CHAPPELL'S PRE-SCHOOL

License #: 1530 Director: SHERRY CHAPPELL Inspection Date: 07/30/2021 Annual/Mid Inspection

Inspector: Tera German

# **Program Administration Violations Cited**

No violations cited

### **Kitchen Violations Cited**

No violations cited.

## **Nutritional Guidelines Violations Cited**

No violations cited.

# **Playground Violations Cited**

- 1. **Out of Compliance:** Playground fence is less than 3 ½ inches from ground surface, in good repair with no gaps and secure gate latch. (Rule 1.11.9(8) Page 60)
- 2. **Out of Compliance:** All bolts on equipment and fences are no more than two threads beyond the nut. (Rule 1.11.9 Page 59)

#### Plan of Correction

1. **POC:** Owner will get maintenance man to come cut bolts on fence down 2 threads beneath the nut and spray paint rusting areas on fence.

Person Responsible: Owner/Director Date for Completion: 2 Weeks August, 13, 2021

#### **Infant Classroom Violations Cited**

1. **Out of Compliance:** Thermometers that are not hazardous to children are placed on interior walls at children's height. (Rule 1.11.8(9) Page 58)

#### Infant Classroom - Classroom Number: 1

1. **POC:** Owner will place thermometer on wall at child's height.

**Person Responsible:** Owner/Director **Date for Completion:** Monday, August 2, 2021

#### **Twos Classroom Violations Cited**

2 Year Old - Classroom Number: 2

No violations cited.

Twos Classroom - Classroom Number: 2

#### **Preschool Classroom Violations Cited**

All Purpose - Classroom Number: 3

No violations cited

Preschool Classroom - Classroom Number: 3

4-5 Year Old - Classroom Number: 5

No violations cited.

Preschool Classroom - Classroom Number: 5

- 3 Year Old Classroom Number: 4
  - 1. **Out of Compliance:** Evacuation route is posted in classroom. (Rule 1.4.6(d) Page 18)
  - 2. **Out of Compliance:** Thermometers that are not hazardous to children are placed on interior walls at children's height. (Rule 1.11.8(9) Page 58)

#### Preschool Classroom - Classroom Number: 4

1. **POC:** Owner will place evacuation route and thermometer on wall in classroom.

**Person Responsible:** Owner **Date for Completion:** Monday August 2, 2021

### **School Age Room Violations Cited**

### School Age - Classroom Number: 7

- 1. Out of Compliance: Unused electrical outlets are covered by safety plug covers. (Rule 1.11.1 Page 52)
- 2. **Out of Compliance:** Thermometers that are not hazardous to children are placed on interior walls at children's height. (Rule 1.11.8(9) Page 58)

#### School Age Room - Classroom Number: 7

1. **POC:** Owner will place thermometer on wall at child's height and put covers in unused outlets. **Person Responsible:** Owner/Director **Date for Completion:** Monday, August 2, 2021

#### Legend

• COS: Corrected on Site

• POC: Plan of Correction

**Child Care Director Signature** 

SherryChappell

**MSDH Licensure Representative Signature** 

1 2 James