

MISSISSIPPI STATE DEPARTMENT OF HEALTH

Child Care Encounter

District		Date 1. 19. 22.
Name Liberty Head Start	License No. Pendi	ng
Address 400 West Freedom Center/Org	Dive, Liberty	, M539209
Purpose Final	Director Monica Ro	binson
Mileage Start	Mileage End	0.01
County Amite	Telephone No. 601 657 43	288
Time In Time Out	Total Time	
Findings/Comments Arrived at Facili director Stated Purpo	ity and met v	vith s visit.
Item Needed: Carbon		
Playground: Protrudin		
Please provide picto	ure via email a	and
Thanks for all you do	and continue to	Keep
Safe!		
		

Mica Holling Center Directof Designee/Individual

Mississippi State Department of Health

Child Care Representative
Revised 6-24-09

White Copy - Facility File Yellow Copy - Operator



Mississippi State Department of Health Child Care Facility Inspection

County Amite	Date_ 1.19. 2022
Facility Name Liberty Head Start	License Number pending
Purpose_PUSIDIC FINAI	Capacity 8 /
All Items In Red Are Critical Qualified director present Proper staff to child ratio present	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities
Room and playground capacity met Center capacity met License/complaint visible Certified food manager	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair
Sanitation Approved Garbage and garbage bins maintained Vector control maintained Water system approved and functioning Waste water system approved	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available, and functioning
and functioning Food service approved Possible Monetary Penalty	Electrical outlets protected Large appliances located properly Sinks and toilets working properly
Monetary Penalty 5	Hot water at all sinks, not to exceed 120° Children barred from kitchen Vending machine snacks meet nutritional guidelines, if present
3, \$ 4 \$	Exits, doors and fastening devices single action approved and in good working order
Age/Child/Staff Name	Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and in good working order
1. No children present	First aid kits stocked and easily accessible
3. 4.	Playground area clean, shaded, well drained and equipped and fence in good repair
5.	Playground equipment meets standards
6 7.	Pool area clean, fenced, and adequately maintained
m. 101	Diaper changing stations adequate in number and each fully supplied (number)
Center Director/Individual	Child Care Representative
White Copy - Facility File Yellow Copy - Facility Operator Mississippi State Department of Health	12-10-08 (Pra Form No. 28)

Food Service Facility Inspection Results

PIMS ID Fac	ility Name, Address Start Devil Head Start West Freedom	Or. Liberty 115 39209	Date 1. 19.2022
CRITICAL VIOLATIONS		CORRECTION PLAN AND SCHEDULE	
No critical V cited on to			
		Patricia Freal	ServSafe
☐ 92020 Scheduled	☐ 92010 Permit No Charge		icence Number
☐ 92030 Followup	92015 Permit 1 \$30.00	E	Q. 11/18/2024
☐ 92040 Complaint ☐ 92050 Consultation	☐ 92011 Permit 2 \$100.00 ☐ 92012 Permit 3 \$150.00	2	/ /
92070 Plan Review/Const.	☐ 92012 Permit 3 \$150.00 ☐ 92013 Permit 4 \$200.00		
92080 No Inspection			
92090 Restaurant Training	3	Facility Signature	11 Pohram
Permit Date	Environmentalist Code	Environmentalist Signature	Herd Hours
Please Remit within 10 days to:		White Copy - Facility Yellow Copy - PIMS Pink Copy- Environmentalist	

Child Care Licensure Playground Checklist

Cer	nter]	Name	Li	berty Head Start Inspection Date 1.19.2022
YES	S NO	O N/A	i.	
×			1.	Playground fence less than 3 1/2" from surface. (Rule 1.11.9 (8), pg 60) In good repair, with no gaps? (Rule 1.11.9 (8), pg 60)
P			2.	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 60)
No.			3.	Is surfacing adequate? If not, where is it inadequate? (CPSC, Z.4.2, pg 9-10 & 4.3)
A			4.	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 59)
7			5.	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2(5), pg 10 & Rule 1.11.11 (4), pg 61)
7			6.	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 46)
7			7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 16-17)
A			8.	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 59)
/d			9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 16)
×			10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 41)
		Þ	11.	If swings are present, are S-hooks in good repair? If not, state deficiency (CPSC 3.2, pg 14;
1				2.5.2, pg 1 & 5.3.8.1, pg 37)
P			12.	If slide is present, is exit height/exit zone adequate? If not, state deficiency (CPSC5.3.6.4-5 pgs 34-35)
		A	13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2 & CPSC 5.3.7. pg 36-37)
1			14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate
				(Rule 1.10.2, pg 46
	1			& CPSC 2.2.6, pg 6)
	Z		15.	Is playground area clean & free of hazards? If not, state deficiency. Control of the control
# 0			16.	Is adequate shade present on the playground? (Rule 1.11.9 (7), pg 60 & CPSC 2.1.1, pg 5)
z c			17.	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 46 &
		1	-	CPSC 3.6, pg 16-17)
		P	18.	Is wood smooth? Documentation provided that wood has been properly treated. (CPSC 2.5.5, pg 15)
irector	41	Per	vi C6	Robinson Licensing Official School Sond
				Wa Orlumian