

Yalobusha General Hosp. D/B/A Cotten Candy Kids Center 219 Frostland Drive, Water Valley, MS 38965 License # 7124 Capacity 88

Purpose_

Center capacity met License/complaint visible Certified food manager

Sanitation Approved

Vector control maintained

and functioning Food service approved

3.

4.5.6.

Waste water system approved

Possible Monetary Penalty

All Items In Red Are Critical
Qualified director present
Proper staff to child ratio present
Room and playground capacity met

Garbage and garbage bins maintained

Water system approved and functioning

MISSISSIPPI STATE DEPARTMENT OF HEALTH Child Care Facility Inspection					
	Date 0//12/202	1			
	1 1	/			
	License Number				
Car	pacity				
In Out COS N/A	Other Items - Must be corrected Children's belongings separated/stored Evacuation plans posted Menus posted and served Plan of activities	In Now You	Out	COS	N/A
	Building and Grounds Walls, ceilings, floors, toys, equipment clean and in good repair	A			
	Lighting approved Heating/cooling approved Ventilation adequate Glass approved and shielded Telephone on premises, available,	NASAS.			
	and functioning Electrical outlets protected Large appliances located properly	多区			
Monetary Penalty \$	Sinks and toilets working properly Hot water at all sinks, not to exceed 120° Children barred from kitchen	外食			
\$ \$	Vending machine snacks meet nutritional guidelines, if present Exits, doors and fastening devices single action approved and in good				×
\$	working order Exits unobstructed	XX			
Name	Required smoke detectors, carbon monoxide monitors, fire extinguishers and thermometers placed properly and in good working order	以	. 🗆		
7/142	First aid kits stocked and easily accessible	X			
143#4	Playground area clean, shaded, well drained and equipped and fence in good repair	X			
#6 = 1	Playground equipment meets standards	X			
1 ± 0 P ± 9	Pool area clean, fenced, and adequately maintained				×
7	Diaper changing stations adequate in number and each fully supplied	,			

Center Director/Individual

White Copy - Facility File

Yellow Copy - Facility Operator

Mississippi State Department of Health

Age/Child/Staff

(number _

WChild Care Representative

Page	of	



MISSISSIPPI STATE DEPARTMENT OF HEALTH

District	Yalobusha General Hosp. D/B/A Cotton Candy Kids Center	Date <u>01/12/2021</u>
Name	219 Frostland Drive	
Address	Water Valley, MS 38965 License # 7124 Yalobusha	
Purpose MA - LICOU	Director Steptanie	2 Fergauson
Mileage Start	Mileage End	
County		1-0340
Time In 10,10	ne Out_/&;	
Findings/Comments According to the Construction of the Constructio	eco met With Steph	stron. The
Sub-Chapter: 6-Sac	MING BOOKS.	Frank Man N. V. I Charlo
mountelle a nat 121 gent facto of fortale stell and Stell and children alphabetreal orde		ach Kleniky Small S of And MSDH Co. (MSDH FORM#121) f. The patobox small I costes of both U Je I Mero in I staff and andren
Androce Jases of	m absertations and re	DRIVE OF ISTAFF
Thirtheon (13) Childre	n. Children and Staff i	orth no fallorm
the directors will all bare a valled and of each ma a current 121 for	Donswe that ach At MSDHIBITORM BY Ch BATH. Each and and B m Juface their where	taffard Ohrdren Schon, at the telf will have Hoote,
Relicensing aff match the duries	rcical Observed Day	Moster didnit
Center Director/Designee/Individual	Child Care Representative	White Copy - Facility File Yellow Copy - Operator



Date 01/12/2021.

Facility Name Valobusha General HSP License No. 1124. All aborden and Stelf must have a current appropriate of Acet That without a proposed
Fitcher received lettre grade A.
Unid care questionnaire left with duester
monetary penalty. Repeated Walertions may result in the southern of a monetary penalty, suppension, or recording of the licenster.
TIPMINI TONDOM Center Director/Designee/Individual Child Care Representative White Copy - Facility File Yellow Copy - Operator

Food Service Facility Inspection Results

Yalobusha General Hosp. D/B/A

Cotton Candy Kids Center PIMS ID Facility Name 219 Frostland Drive Water Valley, MS 38965 License # 7124 Yalobusha **CRITICAL VIOLATIONS** ION PLAN AND SCHEDULE NO entical violations during to day inspettor Licence Number Certified Manager ☐ 92020 Scheduled ☐ 92010 Permit No Charge ☐ 92030 Followup ☐ 92015 Permit 1 \$30.00 ☐ 92040 Complaint ☐ 92011 Permit 2 \$100.00 ☐ 92050 Consultation ☐ 92012 Permit 3 \$150.00 92013 Permit 4 \$200.00 ☐ 92070 Plan Review/Const. ☐ 92080 No Inspection Facility Signature ☐ 92090 Restaurant Training Environmentalist Signature Environmentalist Code Permit Date White Copy - Facility Please Remit within 10 days to: Yellow Copy - PIMS Pink Copy- Environmentalist

Marin

	Yalobusha General Hosp. D/B/A
Center Name	Cotton Candy Kids Center
Conton Training	219 Frostland Drive Inspection Date 6/1/2 1908
YES NO N/A	vucci valley, 1913 38905
	License # 7124 Yalobusha Figyground renderess than 3/2 from surface. (Rule 1.11.9 (8), pg 48) In good repair, with no gaps? (Rule 1.11.9 (8), pg 48)
Ø 0 0 2.	(-), F8 (-)
	2 entrances/exits, with one being remote from the building? (Rule 1.11.9 (8), pg 48)
,	Is surfacing adequate? If not, where is it inadequate? (CPSC, 2.4.2, pg8)
A 0 0 4,	AC units, high-voltage cabling/wires inaccessible? (Rule 1.11.9 (5), pg 47)
Ø □ □ 5,	No standing water present on playground or in/on playground equipment or walkways? (CPSC 2.4.2.2-5, pg 10)
\nearrow \Box \Box \Box \Box \Box \Box \Box	Toys & equipment in good repair? (none broken/deteriorating) (Rule 1.10.2 (2), pg 36)
A 0 0 7.	Sidewalks provide smooth walking surface? (no trip hazards) (CPSC 3.6, pg 15)
▼ □ □ 8.	All bolts on equipment & force (2.4)
- -	All bolts on equipment & fence <2 threads beyond the nut? Are all bolts and fencing twists/wires facing away from the playground area? (Rule 1.11.9 (5), pg 47)
A D D 9.	Tree limbs at least 7ft. above play surfaces? Is fence free of brush/overgrowth? (CPSC 3.4, 3.5, pg 15)
Ø □ □ 10.	Are use zones adequate? If not, where are they inadequate? (CPSC 5.3.9, pg 40)
0 0 🕅 11.	If swings are present, are S-hooks in good repair? If not, state deficiency
Ø □ 12.	(CPSC 3.2, pg/3)
, , , , , , , , , , , , , , , , , , , 	17 Since is present, is exit height/exit zone adequate? If not, state deficiency (CPSC 3.6.4-5, nos. 24.25)
P 0 0 13.	Are spring rockers a minimum of 6 ft. apart? (ASTM 9.5.1.2, pg 15)
A 0 0 14.	Is age-appropriate equipment being used? If not, state which pieces are inappropriate
	Is playground area clean & free of hazards? If not, state deficiency.
Z 0 0 16.	(Rule 1.11.11 (1), pg 49)
· /	is adequate shade present on the playground? (CPSC 2.1.1, pg 5)
	Are concrete footings located at least 6" beneath the surface? (Rule 1.10.2 (2), pg 36)
	is wood smooth? Documentation provided that wood has been properly treated. (CDSC)
Dr. 1.	/ \
Director MIPHOL	We Lengthan Licensing Official Kolma Shape